



Collected on: Feb 09 2022 10:31

Received on: Feb 10 2022 08:30

Reported on: Feb 11 2022 09:44

Ordered by: VANCOUVER COASTAL HEALTH (SECHLT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHLT)

Printed on: 2022-02-15 11:00

Page 1 of 1

Test	Flag	Result	Reference Range - Units
------	------	--------	-------------------------

Sample: GIBSONS WATER SYSTEM
SITE 13 PARKLAND RESERVOIR SAMPLE PORT LOW

Environmental Report

Environmental Water Samplings

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	Parkland	
System Type	WS1A	
Specimen Source	Deep Well	
Site Treatment	No	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL



Collected on: Feb 09 2022 09:25

Received on: Feb 10 2022 08:30

Reported on: Feb 11 2022 09:44

Ordered by: VANCOUVER COASTAL HEALTH (SECHLT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHLT)

Printed on: 2022-02-15 11:00

Page 1 of 1

Test	Flag	Result	Reference Range - Units
------	------	--------	-------------------------

Sample: GIBSONS WATER SYSTEM
SITE 10 SCHOOL ROAD RESERVOIR

Environmental Report

Environmental Water Samplings

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	School Road	
System Type	WS1A	
Specimen Source	Deep Well	
Site Treatment	No	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL



Collected on: Feb 09 2022 09:37

Received on: Feb 10 2022 08:30

Reported on: Feb 11 2022 09:44

Ordered by: VANCOUVER COASTAL HEALTH (SECHLT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHLT)

Printed on: 2022-02-15 11:00

Page 1 of 1

Test	Flag	Result	Reference Range - Units
------	------	--------	-------------------------

Sample: GIBSONS WATER SYSTEM
SITE 5 GIBSONS WAY

Environmental Report

Environmental Water Samplings

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	Highway 101	
System Type	WS1A	
Specimen Source	Combined	
Site Treatment	Yes	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL



Collected on: Feb 09 2022 08:49

Received on: Feb 10 2022 08:30

Reported on: Feb 11 2022 09:44

Ordered by: VANCOUVER COASTAL HEALTH (SECHLT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHLT)

Printed on: 2022-02-15 11:00

Page 1 of 1

Test	Flag	Result	Reference Range - Units
------	------	--------	-------------------------

Sample: GIBSONS WATER SYSTEM
SITE 15 ARBUTUS REACH

Environmental Report

Environmental Water Samplings

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	Arbutus Reach	
System Type	WS1A	
Specimen Source	Deep Well	
Site Treatment	No	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL



Collected on: Feb 09 2022 08:40

Received on: Feb 10 2022 08:30

Reported on: Feb 11 2022 09:44

Ordered by: VANCOUVER COASTAL HEALTH (SECHLT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHLT)

Printed on: 2022-02-15 11:00

Page 1 of 1

Test	Flag	Result	Reference Range - Units
------	------	--------	-------------------------

Sample: GIBSONS WATER SYSTEM
SITE 8 FRANKLIN ROAD

Environmental Report

Environmental Water Samplings

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	Franklin Road	
System Type	WS1A	
Specimen Source	Deep Well	
Site Treatment	No	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL



Collected on: Feb 09 2022 10:03

Received on: Feb 10 2022 08:30

Reported on: Feb 11 2022 09:44

Ordered by: VANCOUVER COASTAL HEALTH (SECHLT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHLT)

Printed on: 2022-02-15 11:00

Page 1 of 1

Test	Flag	Result	Reference Range - Units
------	------	--------	-------------------------

Sample: GIBSONS WATER SYSTEM
SITE 6 SHAW ROAD

Environmental Report

Environmental Water Samplings

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	Shaw Road	
System Type	WS1A	
Specimen Source	Deep Well	
Site Treatment	No	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL



Collected on: Feb 09 2022 09:47

Received on: Feb 10 2022 08:30

Reported on: Feb 11 2022 09:44

Ordered by: VANCOUVER COASTAL HEALTH (SECHLT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHLT)

Printed on: 2022-02-15 11:00

Page 1 of 1

Test	Flag	Result	Reference Range - Units
------	------	--------	-------------------------

Sample: GIBSONS WATER SYSTEM
SITE 4 KIWANIS

Environmental Report

Environmental Water Samplings

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	Upper Gibsons	
System Type	WS1A	
Specimen Source	Combined	
Site Treatment	Yes	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL



Collected on: Feb 09 2022 09:03

Received on: Feb 10 2022 08:30

Reported on: Feb 11 2022 09:44

Ordered by: VANCOUVER COASTAL HEALTH (SECHLT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHLT)

Printed on: 2022-02-15 11:00

Page 1 of 1

Test	Flag	Result	Reference Range - Units
------	------	--------	-------------------------

Sample: GIBSONS WATER SYSTEM
SITE 9 BALLS LANE

Environmental Report

Environmental Water Samplings

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	Balls Lane	
System Type	WS1A	
Specimen Source	Deep Well	
Site Treatment	No	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL



Collected on: Feb 09 2022 09:54

Received on: Feb 10 2022 08:30

Reported on: Feb 11 2022 09:44

Ordered by: VANCOUVER COASTAL HEALTH (SECHLT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHLT)

Printed on: 2022-02-15 11:00

Page 1 of 1

Test	Flag	Result	Reference Range - Units
------	------	--------	-------------------------

Sample: GIBSONS WATER SYSTEM
SITE 14 DAVIS ROAD

Environmental Report

Environmental Water Samplings

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	Davis Road	
System Type	WS1A	
Specimen Source	Deep Well	
Site Treatment	No	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL



Collected on: Feb 09 2022 10:20

Received on: Feb 10 2022 08:30

Reported on: Feb 11 2022 09:44

Ordered by: VANCOUVER COASTAL HEALTH (SECHLT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHLT)

Printed on: 2022-02-15 11:00

Page 1 of 1

Test	Flag	Result	Reference Range - Units
------	------	--------	-------------------------

Sample: GIBSONS WATER SYSTEM
SITE 2 PARK ROAD

Environmental Report

Environmental Water Samplings

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	Park Road	
System Type	WS1A	
Specimen Source	Combined	
Site Treatment	Yes	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL



Collected on: Feb 09 2022 09:15

Received on: Feb 10 2022 08:30

Reported on: Feb 11 2022 09:44

Ordered by: VANCOUVER COASTAL HEALTH (SECHLT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHLT)

Printed on: 2022-02-15 11:00

Page 1 of 1

Test	Flag	Result	Reference Range - Units
------	------	--------	-------------------------

Sample: GIBSONS WATER SYSTEM
SITE 7 ABBS ROAD

Environmental Report

Environmental Water Samplings

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	Abbs Road	
System Type	WS1A	
Specimen Source	Deep Well	
Site Treatment	No	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL