

Reported by: PHSA Environmental

Collected on: Apr 05 2022 10:10

Received on: Apr 06 2022 08:30

Reported on: Apr 07 2022 11:04



Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2022-04-08 08:22

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Page 1 of 1

Test	Flag Result	Reference Range - Units
------	-------------	-------------------------

Sample: GIBSONS WATER SYSTEM
SITE 10 SCHOOL ROAD RESERVOIR

Environmental Report

Environmental Water Samplings

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	School Road	
System Type	WS1A	
Specimen Source	Deep Well	
Site Treatment	No	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental

Collected on: Apr 05 2022 09:30

Received on: Apr 06 2022 08:30

Reported on: Apr 07 2022 11:04



Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2022-04-08 08:22

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Page 1 of 1

Test	Flag Result	Reference Range - Units
------	-------------	-------------------------

Sample: GIBSONS WATER SYSTEM
SITE 13 PARKLAND RESERVOIR SAMPLE PORT LOW

Environmental Report

Environmental Water Samplings

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	Parkland	
System Type	WS1A	
Specimen Source	Deep Well	
Site Treatment	No	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental



Collected on: Apr 05 2022 10:02

Received on: Apr 06 2022 08:30

Reported on: Apr 07 2022 11:04

Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2022-04-08 08:22

Page 1 of 1

Test	Flag Result	Reference Range - Units
------	-------------	-------------------------

Sample: GIBSONS WATER SYSTEM
SITE 6 SHAW ROAD

Environmental Report

Environmental Water Samplings

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	Shaw Road	
System Type	WS1A	
Specimen Source	Deep Well	
Site Treatment	No	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental

Collected on: Apr 05 2022 10:50

Received on: Apr 06 2022 08:30

Reported on: Apr 07 2022 11:04



Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2022-04-08 08:22

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Page 1 of 1

Test	Flag Result	Reference Range - Units
------	-------------	-------------------------

Sample: GIBSONS WATER SYSTEM
SITE 8 FRANKLIN ROAD

Environmental Report

Environmental Water Samplings

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	Franklin Road	
System Type	WS1A	
Specimen Source	Deep Well	
Site Treatment	No	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental



Collected on: Apr 05 2022 10:55

Received on: Apr 06 2022 08:30

Reported on: Apr 07 2022 11:46

Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2022-04-08 08:22

Page 1 of 1

Test	Flag Result	Reference Range - Units
------	-------------	-------------------------

Sample: GIBSONS WATER SYSTEM
SITE 9 BALLS LANE

Environmental Report

Environmental Water Samplings

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	Balls Lane	
System Type	WS1A	
Specimen Source	Deep Well	
Site Treatment	No	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL