

Reported by: PHSA Environmental

Collected on: May 03 2022 08:25

Received on: May 04 2022 08:30

Reported on: May 05 2022 11:10

Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2022-05-06 10:30

Page 1 of 1

BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Flag Result

Reference Range - Units

Sample: GIBSONS WATER SYSTEM

SITE 10 SCHOOL ROAD RESERVOIR

Test

Environmental Report

Reported to:

Environmental Water Samplings

Sample Type Drinking water
Method Membrane Filtration
Environmental Health Officer Darren Molder
Site Address School Road
System Type WS1A
Specimen Source Deep Well

Site Treatment No



Reported by: PHSA Environmental

Provincial Health
Services Authority
Province-wide solutions.
Better health.

Collected on: May 03 2022 08:07 Received on: May 04 2022 08:30 Reported on: May 05 2022 11:18

Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2022-05-06 10:30

Page 1 of 1

BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Flag Result

Reference Range - Units

Sample: GIBSONS WATER SYSTEM

Test

SITE 13 PARKLAND RESERVOIR SAMPLE PORT LOW

Environmental Report

Reported to:

Environmental Water Samplings

Sample Type Drinking water
Method Membrane Filtration
Environmental Health Officer Darren Molder
Site Address Parkland
System Type WS1A
Specimen Source Deep Well

Site Treatment No

Flag Result



Reported by: PHSA Environmental

Collected on: May 03 2022 07:58

Received on: May 04 2022 08:30

Reported on: May 05 2022 11:10

Provincial Health
Services Authority
Province-wide solutions.
Better health.

Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

ASTAL REALTH (SECRELT) Printed on: 2022-05-06 10:30

Page 1 of 1

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Reference Range - Units

Sample: GIBSONS WATER SYSTEM

Test

SITE 6 SHAW ROAD

Environmental Report

Environmental Water Samplings

Sample Type Drinking water
Method Membrane Filtration
Environmental Health Officer Darren Molder
Site Address Shaw Road
System Type WS1A
Specimen Source Deep Well

Site Treatment No



Reported by: PHSA Environmental

Reference Range - Units

Provincial Health Services Authority Province-wide solutions.

Collected on: May 03 2022 07:37 Received on: May 04 2022 08:30 Reported on: May 05 2022 11:10

Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2022-05-06 10:30 BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Flag Result

Page 1 of 1

Sample: GIBSONS WATER SYSTEM SITE 8 FRANKLIN ROAD

Test

Environmental Report

Reported to:

Environmental Water Samplings

Sample Type Drinking water Method Membrane Filtration **Environmental Health Officer** Darren Molder Site Address Franklin Road WS1A System Type

Specimen Source Deep Well

Site Treatment No



Reported by: PHSA Environmental

Collected on: May 03 2022 07:39
Received on: May 04 2022 08:30
Reported on: May 05 2022 11:10

Provincial Health Services Authority Province-wide solutions. Better health.

Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2022-05-06 10:30

BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Page 1 of 1

Test Flag Result Reference Range - Units

Sample: GIBSONS WATER SYSTEM

SITE 9 BALLS LANE

Environmental Report

Reported to:

Environmental Water Samplings

Sample Type Drinking water
Method Membrane Filtration
Environmental Health Officer Darren Molder
Site Address Balls Lane
System Type WS1A
Specimen Source Deep Well

Site Treatment No



Reported by: PHSA Environmental

Collected on: May 11 2022 09:31

Received on: May 12 2022 08:30

Provincial Health Services Authority Province vide solutions. Better freath.

Received on: May 12 2022 08:30 Reported on: May 13 2022 11:21

Ordered by: VANCOUVER COASTAL HEALTH (SECHELT) Printed on: 2022-05-16 08:15

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT) Page 1 of 1

Test Flag Result Reference Range - Units

Sample: GIBSONS WATER SYSTEM

SITE 10 SCHOOL ROAD RESERVOIR

Environmental Report

Environmental Water Samplings

Sample Type Drinking water
Method Membrane Filtration
Environmental Health Officer Darren Molder
Site Address School Road
System Type WS1A
Specimen Source Deep Well

Site Treatment No



Reported by: PHSA Environmental

Collected on: May 11 2022 11:02
Received on: May 12 2022 08:30
Reported on: May 13 2022 11:21

Flag Result

Provincial Health
Services Authority
Province-vide solutions.
Better health.

Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2022-05-16 08:15

BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT) Page 1 of 1

Reference Range - Units

Sample: GIBSONS WATER SYSTEM

Test

SITE 13 PARKLAND RESERVOIR SAMPLE PORT LOW

Environmental Report

Reported to:

Environmental Water Samplings

Sample Type Drinking water
Method Membrane Filtration
Environmental Health Officer Darren Molder
Site Address Parkland
System Type WS1A
Specimen Source Deep Well

Site Treatment No



Reported by: PHSA Environmental

Collected on: May 11 2022 11:22 Received on: May 12 2022 08:30 Reported on: May 13 2022 11:21

Flag Result

Services Authority
Province-vide solutions.
Better health.

Provincial Health

Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2022-05-16 08:15

Page 1 of 1

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Reference Range - Units

Sample: GIBSONS WATER SYSTEM

SITE 14 DAVIS ROAD

Test

Environmental Report

Environmental Water Samplings

Sample Type Drinking water
Method Membrane Filtration
Environmental Health Officer Darren Molder
Site Address Davis Road
System Type WS1A
Specimen Source Deep Well

Site Treatment No



Reported by: PHSA Environmental

Provincial Health Services Authority Province-wide solutions.

Collected on: May 11 2022 08:59 Received on: May 12 2022 08:30 Reported on: May 13 2022 11:21

Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2022-05-16 08:15

Page 1 of 1

BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT) Test Flag Result Reference Range - Units

Sample: GIBSONS WATER SYSTEM SITE 15 ARBUTUS REACH

Environmental Report

Reported to:

Environmental Water Samplings

Sample Type Drinking water Method Membrane Filtration **Environmental Health Officer** Darren Molder Site Address Arbutus Reach WS1A

System Type Specimen Source Deep Well Site Treatment No

Total Coliform Less than 1 Escherichia Coli Less than 1 Count/100mL Count/100mL

Flag Result



Reported by: PHSA Environmental

Collected on: May 11 2022 11:14

Received on: May 12 2022 08:30

Reported on: May 13 2022 11:21

Provincial Health
Services Authority
Province-wide solutions.
Better health.

Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2022-05-16 08:15

Page 1 of 1

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Reference Range - Units

Sample: GIBSONS WATER SYSTEM

Test

SITE 2 PARK ROAD

Environmental Report

Environmental Water Samplings

Sample Type Drinking water
Method Membrane Filtration
Environmental Health Officer Darren Molder
Site Address Park Road
System Type WS1A
Specimen Source Combined
Site Treatment Yes



Reported by: PHSA Environmental

Reference Range - Units

Provincial Health Services Authority Province-wide solutions.

Collected on: May 11 2022 09:47 Received on: May 12 2022 08:30 Reported on: May 13 2022 11:21

Flag Result

Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2022-05-16 08:15 BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Page 1 of 1

Sample: GIBSONS WATER SYSTEM

Test

SITE 4 KIWANIS

Environmental Report

Reported to:

Environmental Water Samplings

Sample Type Drinking water Method Membrane Filtration **Environmental Health Officer** Darren Molder Site Address Upper Gibsons

WS1A System Type Specimen Source Combined Site Treatment Yes



Reported by: PHSA Environmental

Provincial Health Services Authority Province-wide solutions.

Collected on: May 11 2022 09:39 Received on: May 12 2022 08:30 Reported on: May 13 2022 11:21

Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2022-05-16 08:15

Page 1 of 1

BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT) Test Flag Result Reference Range - Units

Sample: GIBSONS WATER SYSTEM

SITE 5 GIBSONS WAY

Environmental Report

Reported to:

Environmental Water Samplings

Sample Type Drinking water Method Membrane Filtration **Environmental Health Officer** Darren Molder Site Address Highway 101 WS1A System Type Specimen Source Combined Site Treatment Yes



Reported by: PHSA Environmental

Provincial Health
Services Authority
Province-vide solutions.
Better health.

Collected on: May 11 2022 09:55 Received on: May 12 2022 08:30 Reported on: May 13 2022 11:21

Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2022-05-16 08:15

Page 1 of 1

BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Flag Result

Reference Range - Units

Sample: GIBSONS WATER SYSTEM

Test

SITE 6 SHAW ROAD

Environmental Report

Reported to:

Environmental Water Samplings

Sample Type Drinking water
Method Membrane Filtration
Environmental Health Officer Darren Molder
Site Address Shaw Road
System Type WS1A
Specimen Source Deep Well

Site Treatment No



Reported by: PHSA Environmental

Collected on: May 11 2022 09:13

Received on: May 12 2022 08:30

Reported on: May 13 2022 11:21

Provincial Health
Services Authority
Province-wide solutions.
Better health.

Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2022-05-16 08:15 Page 1 of 1

Test Flag Result Reference Range - Units

Sample: GIBSONS WATER SYSTEM

SITE 7 ABBS ROAD

Environmental Report

Reported to:

Environmental Water Samplings

Sample Type Drinking water
Method Membrane Filtration
Environmental Health Officer Darren Molder
Site Address Abbs Road
System Type WS1A
Specimen Source Deep Well

Site Treatment No



Reported by: PHSA Environmental

Provincial Health Services Authority Province-wide solutions.

Collected on: May 11 2022 08:47 Received on: May 12 2022 08:30 Reported on: May 13 2022 11:21

Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2022-05-16 08:15

Page 1 of 1

BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT) Test Flag Result Reference Range - Units

Sample: GIBSONS WATER SYSTEM

SITE 8 FRANKLIN ROAD

Environmental Report

Reported to:

Environmental Water Samplings

Sample Type Drinking water Method Membrane Filtration **Environmental Health Officer** Darren Molder Site Address Franklin Road WS1A System Type

Specimen Source Deep Well

Site Treatment No

BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)



Reported by: PHSA Environmental

Provincial Health
Services Authority
Province-wide solutions.
Better health.

Collected on: May 11 2022 09:19 Received on: May 12 2022 08:30 Reported on: May 13 2022 11:21

Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2022-05-16 08:15

Page 1 of 1

Test Flag Result Reference Range - Units

Sample: GIBSONS WATER SYSTEM

SITE 9 BALLS LANE

Environmental Report

Reported to:

Environmental Water Samplings

Sample Type Drinking water
Method Membrane Filtration
Environmental Health Officer Darren Molder
Site Address Balls Lane
System Type WS1A
Specimen Source Deep Well

Site Treatment No



Reported by: PHSA Environmental

Collected on: May 17 2022 07:55

Received on: May 18 2022 08:30

Reported on: May 19 2022 10:35

Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2022-05-20 08:11

Page 1 of 1

BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Flag Result

Reference Range - Units

Sample: GIBSONS WATER SYSTEM

SITE 10 SCHOOL ROAD RESERVOIR

Test

Environmental Report

Reported to:

Environmental Water Samplings

Sample Type Drinking water
Method Membrane Filtration
Environmental Health Officer Darren Molder
Site Address School Road
System Type WS1A
Specimen Source Deep Well

Site Treatment No



Reported by: PHSA Environmental

Collected on: May 17 2022 07:37 Received on: May 18 2022 08:30 Reported on: May 19 2022 10:35

Flag Result

Provincial Health
Services Authority
Province-wide solutions.
Better health.

Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2022-05-20 08:11

Page 1 of 1

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Reference Range - Units

Sample: GIBSONS WATER SYSTEM

Test

SITE 13 PARKLAND RESERVOIR SAMPLE PORT LOW

Environmental Report

Environmental Water Samplings

Sample Type Drinking water
Method Membrane Filtration
Environmental Health Officer Darren Molder
Site Address Parkland
System Type WS1A
Specimen Source Deep Well

Site Treatment No



Reported by: PHSA Environmental

Provincial Health Services Authority Province-wide solutions.

Collected on: May 17 2022 07:46 Received on: May 18 2022 08:30 Reported on: May 19 2022 10:35

Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2022-05-20 08:11 BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Page 1 of 1

Test Flag Result Reference Range - Units

Sample: GIBSONS WATER SYSTEM

SITE 6 SHAW ROAD

Environmental Report

Reported to:

Environmental Water Samplings

Sample Type Drinking water Method Membrane Filtration **Environmental Health Officer** Darren Molder Site Address Shaw Road WS1A System Type Specimen Source Deep Well

Site Treatment No



Reported by: PHSA Environmental

Provincial Health Services Authority Province-wide solutions.

Collected on: May 17 2022 08:53 Received on: May 18 2022 08:30 Reported on: May 19 2022 10:35

Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Page 1 of 1

Printed on: 2022-05-20 08:11

Flag Result

Reference Range - Units

Sample: GIBSONS WATER SYSTEM

SITE 8 FRANKLIN ROAD

Test

Environmental Report

Environmental Water Samplings

Sample Type Drinking water Method Membrane Filtration **Environmental Health Officer** Darren Molder Site Address Franklin Road WS1A System Type

Specimen Source Site Treatment

Total Coliform Less than 1 Count/100mL Escherichia Coli Less than 1 Count/100mL

No

Deep Well



Reported by: PHSA Environmental

Collected on: May 17 2022 08:04 Received on: May 18 2022 08:30 Reported on: May 19 2022 10:35 Provincial Health Services Authority Province-wide solutions.

Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2022-05-20 08:11

BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT) Page 1 of 1 Flag Result

Reference Range - Units

Sample: GIBSONS WATER SYSTEM

Test

SITE 9 BALLS LANE

Environmental Report

Reported to:

Environmental Water Samplings

Sample Type Drinking water Method Membrane Filtration **Environmental Health Officer** Darren Molder Site Address Balls Lane WS1A System Type Specimen Source Deep Well

Site Treatment No



Reported by: PHSA Environmental

Collected on: May 24 2022 09:45

Received on: May 25 2022 08:30

Reported on: May 26 2022 14:48

Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2022-05-27 08:42

Page 1 of 1

BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Flag Result

Reference Range - Units

Sample: GIBSONS WATER SYSTEM

SITE 10 SCHOOL ROAD RESERVOIR

Test

Environmental Report

Reported to:

Environmental Water Samplings

Sample Type Drinking water
Method Membrane Filtration
Environmental Health Officer Darren Molder
Site Address School Road
System Type WS1A
Specimen Source Deep Well

Site Treatment No



Reported by: PHSA Environmental

Provincial Health
Services Authority
Province-vide solutions.
Better health.

Collected on: May 24 2022 08:32 Received on: May 25 2022 08:30

Reported on: May 26 2022 14:48

Flag Result

Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2022-05-27 08:42

Page 1 of 1

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Reference Range - Units

Sample: GIBSONS WATER SYSTEM

Test

SITE 13 PARKLAND RESERVOIR SAMPLE PORT LOW

Environmental Report

Environmental Water Samplings

Sample Type Drinking water

Method Membrane Filtration
Environmental Health Officer Darren Molder
Site Address Parkland
System Type WS1A
Specimen Source Deep Well

Site Treatment No



Printed on: 2022-05-27 08:42

Reference Range - Units

Reported by: PHSA Environmental

Collected on: May 24 2022 09:05 Received on: May 25 2022 08:30 Reported on: May 26 2022 12:26

Provincial Health Services Authority Province-wide solutions.

Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

> BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT) Flag Result

Page 1 of 1

Sample: GIBSONS WATER SYSTEM

SITE 14 DAVIS ROAD

Test

Environmental Report

Reported to:

Environmental Water Samplings

Drinking water Sample Type Method Membrane Filtration **Environmental Health Officer** Darren Molder Site Address Davis Road System Type WS1A Specimen Source Deep Well

Site Treatment No



Reported by: PHSA Environmental

Provincial Health
Services Authority
Province-vide solutions.
Better health.

Collected on: May 24 2022 10:15 Received on: May 25 2022 08:30 Reported on: May 26 2022 14:48

VANCOUVER COASTAL HEALTH (SECHELT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2022-05-27 08:42

Page 1 of 1

Test Flag Result Reference Range - Units

Sample: GIBSONS WATER SYSTEM SITE 15 ARBUTUS REACH

Environmental Report

Ordered by:

Environmental Water Samplings

Sample Type Drinking water
Method Membrane Filtration
Environmental Health Officer Darren Molder
Site Address Arbutus Reach

System Type WS1A
Specimen Source Deep Well

Site Treatment No



Reported by: PHSA Environmental

8:53 Provincial Health
Services Authority
Province ide solutions.
Pater health

Collected on: May 24 2022 08:53 Received on: May 25 2022 08:30 Reported on: May 26 2022 14:50

Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2022-05-27 08:42

Page 1 of 1

BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Test Flag Result Re

Reference Range - Units

Sample: GIBSONS WATER SYSTEM

SITE 2 PARK ROAD

Environmental Report

Reported to:

Environmental Water Samplings

Sample Type Drinking water
Method Membrane Filtration
Environmental Health Officer Darren Molder
Site Address Park Road
System Type WS1A
Specimen Source Combined
Site Treatment Yes



Reported by: PHSA Environmental

Collected on: May 24 2022 09:33

Received on: May 25 2022 08:30

Reported on: May 26 2022 14:48

Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2022-05-27 08:42 T) Page 1 of 1

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Test Flag Result Reference Range - Units

Sample: GIBSONS WATER SYSTEM

SITE 4 KIWANIS

Environmental Report

Environmental Water Samplings

Sample TypeDrinking waterMethodMembrane FiltrationEnvironmental Health OfficerDarren MolderSite AddressUpper Gibsons

System Type WS1A
Specimen Source Combined
Site Treatment Yes

BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)



Reported by: PHSA Environmental

Provincial Health
Services Authority
Province-wide solutions.
Better health.

Collected on: May 24 2022 09:18 Received on: May 25 2022 08:30 Reported on: May 26 2022 14:48

Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2022-05-27 08:42

Page 1 of 1

Test Flag Result Reference Range - Units

Sample: GIBSONS WATER SYSTEM

SITE 5 GIBSONS WAY

Environmental Report

Reported to:

Environmental Water Samplings

Sample Type Drinking water
Method Membrane Filtration
Environmental Health Officer Darren Molder
Site Address Highway 101
System Type WS1A
Specimen Source Combined
Site Treatment Yes



Reported by: PHSA Environmental

Collected on: May 24 2022 09:12

Received on: May 25 2022 08:30

Provincial Health Services Authority
Province ald southors.

Represented on: May 26 2023 14:148

Reported on: May 26 2022 14:48
Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2022-05-27 08:42

Page 1 of 1

BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Flag Result

Reference Range - Units

Sample: GIBSONS WATER SYSTEM

Test

SITE 6 SHAW ROAD

Environmental Report

Reported to:

Environmental Water Samplings

Sample Type Drinking water
Method Membrane Filtration
Environmental Health Officer Darren Molder
Site Address Shaw Road
System Type WS1A
Specimen Source Deep Well

Site Treatment No



Reported by: PHSA Environmental

Provincial Health Services Authority Province-wide solutions.

Collected on: May 24 2022 09:52 Received on: May 25 2022 08:30 Reported on: May 26 2022 14:48

Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2022-05-27 08:42 BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT) Page 1 of 1

Reported to:

Test Flag Result Reference Range - Units

Sample: GIBSONS WATER SYSTEM

SITE 7 ABBS ROAD

Environmental Report

Environmental Water Samplings

Drinking water Sample Type Method Membrane Filtration **Environmental Health Officer** Darren Molder Site Address Abbs Road System Type WS1A Specimen Source Deep Well

Site Treatment No



Printed on: 2022-05-27 08:42

Reference Range - Units

Reported by: PHSA Environmental

Provincial Health Services Authority Province-wide solutions.

Collected on: May 24 2022 10:21 Received on: May 25 2022 08:30 Reported on: May 26 2022 14:48

Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Flag Result

Page 1 of 1

Sample: GIBSONS WATER SYSTEM

SITE 8 FRANKLIN ROAD

Test

Environmental Report

Reported to:

Environmental Water Samplings

Drinking water Sample Type Method Membrane Filtration **Environmental Health Officer** Darren Molder Site Address Franklin Road System Type WS1A

Specimen Source Deep Well Site Treatment No



Reported by: PHSA Environmental

Provincial Health Services Authority Province-wide solutions.

Collected on: May 24 2022 10:44 Received on: May 25 2022 08:30 Reported on: May 26 2022 14:48

Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT) Printed on: 2022-05-27 08:42 Page 1 of 1

Test Flag Result Reference Range - Units

Sample: GIBSONS WATER SYSTEM

SITE 9 BALLS LANE

Environmental Report

Environmental Water Samplings

Drinking water Sample Type Method Membrane Filtration **Environmental Health Officer** Darren Molder Site Address Balls Lane System Type WS1A Specimen Source Deep Well

Site Treatment No



Reported by: PHSA Environmental

Collected on: May 24 2022 10:37

Received on: May 25 2022 08:30

Reported on: May 26 2022 14:48

Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2022-05-27 08:42

Page 1 of 1

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Flag Result

Reference Range - Units

Sample: GIBSONS WATER SYSTEM

Test

WELL 1

Environmental Report

Environmental Water Samplings

Sample Type Drinking water
Method Membrane Filtration
Environmental Health Officer Darren Molder
Site Address Gower Point Road

System Type WS1A
Specimen Source Deep Well

Site Treatment No



Reported by: PHSA Environmental

Collected on: May 24 2022 10:05 Received on: May 25 2022 08:30 Reported on: May 26 2022 14:48 Provincial Health Services Authority Province-wide solutions. Better health.

Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2022-05-27 08:42

Page 1 of 1

Test Flag Result Reference Range - Units

Sample: GIBSONS WATER SYSTEM

WELL 3

Environmental Report

Reported to:

Environmental Water Samplings

Sample Type Drinking water
Method Membrane Filtration
Environmental Health Officer Darren Molder

Site Address Winn T Gower Point Road

System Type WS1A
Specimen Source Deep Well
Site Treatment No



Reported by: PHSA Environmental

Collected on: May 24 2022 10:38 Received on: May 25 2022 08:30 Reported on: May 26 2022 14:48 Provincial Health Services Authority Province-wide solutions.

Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2022-05-27 08:42 BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Page 1 of 1

Test Flag Result Reference Range - Units

Sample: GIBSONS WATER SYSTEM

WELL 4

Environmental Report

Reported to:

Environmental Water Samplings

Drinking water Sample Type Method Membrane Filtration **Environmental Health Officer** Darren Molder Gower Point Road Site Address

System Type WS1A Specimen Source Deep Well

Site Treatment No