

Reported by: PHSA Environmental

Collected on: Aug 03 2022 09:55 Received on: Aug 04 2022 08:30 Reported on: Aug 05 2022 11:31

Provincial Health Services Authority Province-wide solutions.

Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2022-08-08 08:13 BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Page 1 of 1

Test Flag Result Reference Range - Units

Sample: GIBSONS WATER SYSTEM

SITE 10 SCHOOL ROAD RESERVOIR

## **Environmental Report**

Reported to:

## **Environmental Water Samplings**

Sample Type Drinking water Method Membrane Filtration **Environmental Health Officer** Darren Molder Site Address School Road WS1A System Type Specimen Source Deep Well

Site Treatment No



Reported by: PHSA Environmental

Provincial Health
Services Authority
Province-vide solutions.
Better health.

Collected on: Aug 03 2022 10:10 Received on: Aug 04 2022 08:30 Reported on: Aug 05 2022 11:17

Flag Result

Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2022-08-08 08:13

Page 1 of 1

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Reference Range - Units

Sample: GIBSONS WATER SYSTEM

Test

SITE 13 PARKLAND RESERVOIR SAMPLE PORT LOW

# **Environmental Report**

# **Environmental Water Samplings**

Sample Type Drinking water

Method Membrane Filtration
Environmental Health Officer Darren Molder
Site Address Parkland
System Type WS1A
Specimen Source Deep Well

Site Treatment No Total Coliform 2

Flag Result



Reported by: PHSA Environmental

Collected on: Aug 03 2022 10:35

Received on: Aug 04 2022 08:30

Reported on: Aug 05 2022 11:31

Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2022-08-08 08:13

Page 1 of 1

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Reference Range - Units

Sample: GIBSONS WATER SYSTEM

Test

SITE 6 SHAW ROAD

# **Environmental Report**

**Environmental Water Samplings** 

Sample Type Drinking water
Method Membrane Filtration
Environmental Health Officer Darren Molder
Site Address Shaw Road
System Type WS1A
Specimen Source Deep Well

Site Treatment No



Reported by: PHSA Environmental

Provincial Health
Services Authority
Province side on Services Suthority
Provincial Health
Services Authority
Provincial Health

Collected on: Aug 03 2022 09:35
Received on: Aug 04 2022 08:30
Reported on: Aug 05 2022 11:31

Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2022-08-08 08:13

Page 1 of 1

BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Flag Result

Reference Range - Units

Sample: GIBSONS WATER SYSTEM SITE 8 FRANKLIN ROAD

Test

# **Environmental Report**

Reported to:

**Environmental Water Samplings** 

Sample Type Drinking water
Method Membrane Filtration
Environmental Health Officer Darren Molder
Site Address Franklin Road
System Type WS1A

Specimen Source Site Treatment

Total ColiformLess than 1Count/100mLEscherichia ColiLess than 1Count/100mL

No

Deep Well



Reported by: PHSA Environmental

Provincial Health Services Authority Province-wide solutions.

Collected on: Aug 03 2022 09:45 Received on: Aug 04 2022 08:30 Reported on: Aug 05 2022 11:31

Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2022-08-08 08:13

Page 1 of 1

BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT) Test Flag Result Reference Range - Units

Sample: GIBSONS WATER SYSTEM

SITE 9 BALLS LANE

# **Environmental Report**

Reported to:

**Environmental Water Samplings** 

Sample Type Drinking water Method Membrane Filtration **Environmental Health Officer** Darren Molder Site Address Balls Lane WS1A System Type Specimen Source Deep Well

Site Treatment No



Reported by: PHSA Environmental

Provincial Health
Services Authority
Province-vide solutions.
Better health.

Collected on: Aug 08 2022 09:19 Received on: Aug 09 2022 08:30 Reported on: Aug 10 2022 09:38

Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

RE REALTH (SECHELT) Printed on: 2022-08-11 08:26

Page 1 of 1

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Test Flag Result Reference Range - Units

Sample: GIBSONS WATER SYSTEM

SITE 10 SCHOOL ROAD RESERVOIR

#### **Environmental Report**

# **Environmental Water Samplings**

Sample Type Drinking water
Method Membrane Filtration
Environmental Health Officer Darren Molder
Site Address School Road
System Type WS1A
Specimen Source Deep Well

Site Treatment No Total Coliform 1



Reported by: PHSA Environmental

Provincial Health Services Authority Province-wide solutions.

Collected on: Aug 08 2022 09:31 Received on: Aug 09 2022 08:30 Reported on: Aug 10 2022 10:20

Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2022-08-11 08:26

Page 1 of 1

BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT) Flag Result

Reference Range - Units

Sample: GIBSONS WATER SYSTEM

Test

SITE 13 PARKLAND RESERVOIR SAMPLE PORT LOW

## **Environmental Report**

Reported to:

**Environmental Water Samplings** 

Sample Type Drinking water Method Membrane Filtration **Environmental Health Officer** Darren Molder Site Address Parkland WS1A System Type Specimen Source Deep Well

Site Treatment No **Total Coliform** 

Count/100mL 1 Escherichia Coli Less than 1 Count/100mL



Reported by: PHSA Environmental

Collected on: Aug 08 2022 11:11

Received on: Aug 09 2022 08:30

Reported on: Aug 10 2022 10:30

Provincial Health
Services Authority
Province-wide solutions.
Better health.

Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2022-08-11 08:26 Page 1 of 1

Test Flag Result Reference Range - Units

Sample: GIBSONS WATER SYSTEM

SITE 14 DAVIS ROAD

## **Environmental Report**

Reported to:

**Environmental Water Samplings** 

Sample Type Drinking water
Method Membrane Filtration
Environmental Health Officer Darren Molder
Site Address Davis Road
System Type WS1A
Specimen Source Deep Well

Site Treatment No



Reported by: PHSA Environmental

Collected on: Aug 08 2022 10:16 Received on: Aug 09 2022 08:30 Reported on: Aug 10 2022 10:30

Provincial Health Services Authority Province-wide solutions.

Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2022-08-11 08:26 BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Page 1 of 1

Test Flag Result Reference Range - Units

Sample: GIBSONS WATER SYSTEM SITE 15 ARBUTUS REACH

**Environmental Report** 

Reported to:

**Environmental Water Samplings** 

Sample Type Drinking water Method Membrane Filtration **Environmental Health Officer** Darren Molder Site Address Arbutus Reach

WS1A System Type Specimen Source Deep Well Site Treatment No



Reported by: PHSA Environmental

Provincial Health Services Authority Province-wide solutions.

Collected on: Aug 08 2022 11:02 Received on: Aug 09 2022 08:30 Reported on: Aug 10 2022 10:30

Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2022-08-11 08:26 BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Page 1 of 1

Test Flag Result Reference Range - Units

Sample: GIBSONS WATER SYSTEM

SITE 2 PARK ROAD

# **Environmental Report**

Reported to:

**Environmental Water Samplings** 

Sample Type Drinking water Method Membrane Filtration **Environmental Health Officer** Darren Molder Site Address Park Road WS1A System Type Specimen Source Combined Site Treatment Yes



Reported by: PHSA Environmental

Provincial Health Collected on: Aug 08 2022 08:30 Services Authority Province-wide solutions.

Received on: Aug 09 2022 08:30 Reported on: Aug 10 2022 10:30

Ordered by: VANCOUVER COASTAL HEALTH (SECHELT) Printed on: 2022-08-11 08:26 Reported to:

BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT) Page 1 of 1

Test Flag Result Reference Range - Units

Sample: GIBSONS WATER SYSTEM

SITE 4 KIWANIS

## **Environmental Report**

**Environmental Water Samplings** 

Sample Type Drinking water Method Membrane Filtration **Environmental Health Officer** Darren Molder Site Address Upper Gibsons

WS1A System Type Specimen Source Combined Site Treatment Yes



Reported by: PHSA Environmental

Provincial Health
Services Authority
Province-vide solutions.
Better health.

Collected on: Aug 08 2022 10:44
Received on: Aug 09 2022 08:30
Reported on: Aug 10 2022 10:30

Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2022-08-11 08:26

Page 1 of 1

BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Test Flag Result Ref

Reference Range - Units

Sample: GIBSONS WATER SYSTEM

SITE 5 GIBSONS WAY

## **Environmental Report**

Reported to:

**Environmental Water Samplings** 

Sample Type Drinking water
Method Membrane Filtration
Environmental Health Officer Darren Molder
Site Address Highway 101
System Type WS1A
Specimen Source Combined
Site Treatment Yes



Reported by: PHSA Environmental

Provincial Health Services Authority Province-wide solutions. Better health.

Collected on: Aug 08 2022 11:17 Received on: Aug 09 2022 08:30 Reported on: Aug 10 2022 10:30

Flag Result

Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2022-08-11 08:26 Γ) Page 1 of 1

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Reference Range - Units

Sample: GIBSONS WATER SYSTEM

Test

SITE 6 SHAW ROAD

## **Environmental Report**

**Environmental Water Samplings** 

Sample Type Drinking water
Method Membrane Filtration
Environmental Health Officer Darren Molder
Site Address Shaw Road
System Type WS1A
Specimen Source Deep Well

Site Treatment No



Reported by: PHSA Environmental

Collected on: Aug 08 2022 10:36

Received on: Aug 09 2022 08:30

Reported on: Aug 10 2022 10:30

Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2022-08-11 08:26

Page 1 of 1

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT) Page

Test Flag Result Reference

Reference Range - Units

Sample: GIBSONS WATER SYSTEM

SITE 7 ABBS ROAD

## **Environmental Report**

**Environmental Water Samplings** 

Sample Type Drinking water
Method Membrane Filtration
Environmental Health Officer Darren Molder
Site Address Abbs Road
System Type WS1A
Specimen Source Deep Well

Site Treatment No



Reported by: PHSA Environmental

Provincial Health Services Authority Province-wide solutions.

Collected on: Aug 08 2022 10:09 Received on: Aug 09 2022 08:30 Reported on: Aug 10 2022 10:30

Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2022-08-11 08:26 BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Page 1 of 1

Test Flag Result Reference Range - Units

Sample: GIBSONS WATER SYSTEM SITE 8 FRANKLIN ROAD

**Environmental Report** 

Reported to:

**Environmental Water Samplings** 

Sample Type Drinking water Method Membrane Filtration **Environmental Health Officer** Darren Molder Site Address Franklin Road WS1A System Type

Specimen Source Deep Well Site Treatment No

Flag Result



Reported by: PHSA Environmental

Collected on: Aug 08 2022 10:28

Received on: Aug 09 2022 08:30

Reported on: Aug 10 2022 10:30

Provincial Health
Services Authority
Province-wide solutions.
Better health.

Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2022-08-11 08:26 Page 1 of 1

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Reference Range - Units

Test

Sample: GIBSONS WATER SYSTEM SITE 9 BALLS LANE

# **Environmental Report**

**Environmental Water Samplings** 

Sample Type Drinking water
Method Membrane Filtration
Environmental Health Officer Darren Molder
Site Address Balls Lane
System Type WS1A
Specimen Source Deep Well

Site Treatment No



Printed on: 2022-08-15 15:36

Reported by: PHSA Environmental

Page 1 of 1

Provincial Health Services Authority Province-wide solutions

Received on: Aug 12 2022 08:30 Reported on: Aug 13 2022 09:09

Collected on: Aug 11 2022 08:29

VANCOUVER COASTAL HEALTH (SECHELT)

BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Test Flag Result Reference Range - Units

Sample: GIBSONS WATER SYSTEM

SITE 10 SCHOOL ROAD RESERVOIR

**Environmental Report** 

Ordered by:

Reported to:

**Environmental Water Samplings** 

Sample Type Drinking water Method Membrane Filtration **Environmental Health Officer** Darren Molder Site Address School Road System Type WS1A Specimen Source Deep Well

Site Treatment No

Collected on: Aug 11 2022 08:44

Received on: Aug 12 2022 08:30



Printed on: 2022-08-15 15:36

Reported by: PHSA Environmental

Page 1 of 1

Provincial Health Services Authority Province-wide solutions

Reported on: Aug 13 2022 09:09 Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Test Flag Result Reference Range - Units

Sample: GIBSONS WATER SYSTEM

SITE 13 PARKLAND RESERVOIR SAMPLE PORT LOW

**Environmental Report** 

Reported to:

**Environmental Water Samplings** 

Drinking water Sample Type Method Membrane Filtration **Environmental Health Officer** Darren Molder Site Address Parkland System Type WS1A Specimen Source Deep Well

Site Treatment No



Reported by: PHSA Environmental

Provincial Health
Services Authority
Province-vide solutions.
Better health.

Collected on: Aug 16 2022 08:49
Received on: Aug 17 2022 08:30
Reported on: Aug 18 2022 15:11

Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

(SECHELI) Printed on: 2022-08-22 09:12

Page 1 of 1

BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Flag Result

Reference Range - Units

Sample: GIBSONS WATER SYSTEM

SITE 10 SCHOOL ROAD RESERVOIR

Test

## **Environmental Report**

Reported to:

**Environmental Water Samplings** 

Sample Type Drinking water
Method Membrane Filtration
Environmental Health Officer Darren Molder
Site Address School Road
System Type WS1A
Specimen Source Deep Well

Site Treatment No



Reported by: PHSA Environmental

Provincial Health
Services Authority
Province-vide solutions.
Better health.

Collected on: Aug 16 2022 09:16 Received on: Aug 17 2022 08:30 Reported on: Aug 18 2022 15:11

Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2022-08-22 09:12

Page 1 of 1

BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Flag Result

Reference Range - Units

Sample: GIBSONS WATER SYSTEM

Test

SITE 13 PARKLAND RESERVOIR SAMPLE PORT LOW

#### **Environmental Report**

Reported to:

## **Environmental Water Samplings**

Sample Type Drinking water

Method Membrane Filtration
Environmental Health Officer Darren Molder
Site Address Parkland
System Type WS1A
Specimen Source Deep Well

Site Treatment No



Reported by: PHSA Environmental

Provincial Health Services Authority Province-wide solutions.

Collected on: Aug 16 2022 09:02 Received on: Aug 17 2022 08:30 Reported on: Aug 18 2022 15:11

Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2022-08-22 09:12 BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Page 1 of 1

Test Flag Result Reference Range - Units

Sample: GIBSONS WATER SYSTEM

SITE 6 SHAW ROAD

## **Environmental Report**

Reported to:

**Environmental Water Samplings** 

Drinking water Sample Type Method Membrane Filtration **Environmental Health Officer** Darren Molder Site Address Shaw Road System Type WS1A Specimen Source Deep Well

Site Treatment No



Reported by: PHSA Environmental

Provincial Health
Services Authority
Province-wide solutions.
Better health.

Collected on: Aug 16 2022 08:23 Received on: Aug 17 2022 08:30 Reported on: Aug 18 2022 15:11

Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2022-08-22 09:12

Page 1 of 1

BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Flag Result

Reference Range - Units

Sample: GIBSONS WATER SYSTEM

SITE 8 FRANKLIN ROAD

Test

## **Environmental Report**

Reported to:

**Environmental Water Samplings** 

Sample Type Drinking water
Method Membrane Filtration
Environmental Health Officer Darren Molder
Site Address Franklin Road
System Type WS1A

Specimen Source Deep Well Site Treatment No



Reported by: PHSA Environmental

Provincial Health
Services Authority
Province-wide solutions.
Better health.

Collected on: Aug 16 2022 08:37 Received on: Aug 17 2022 08:30 Reported on: Aug 18 2022 15:11

Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2022-08-22 09:12

Page 1 of 1

BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Test Flag Result Re

Reference Range - Units

Sample: GIBSONS WATER SYSTEM

SITE 9 BALLS LANE

# **Environmental Report**

Reported to:

**Environmental Water Samplings** 

Sample Type Drinking water
Method Membrane Filtration
Environmental Health Officer Darren Molder
Site Address Balls Lane
System Type WS1A
Specimen Source Deep Well

Site Treatment No



Reported by: PHSA Environmental

Reference Range - Units

Provincial Health Services Authority Province-wide solutions.

Collected on: Aug 22 2022 09:45 Received on: Aug 23 2022 08:30 Reported on: Aug 24 2022 13:49

Flag Result

Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2022-08-26 08:36 BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Page 1 of 1

Sample: GIBSONS WATER SYSTEM

SITE 10 SCHOOL ROAD RESERVOIR

Test

# **Environmental Report**

Reported to:

**Environmental Water Samplings** 

Drinking water Sample Type Method Membrane Filtration **Environmental Health Officer** Darren Molder Site Address School Road System Type WS1A Specimen Source Deep Well

Site Treatment No



Reported by: PHSA Environmental

Provincial Health Services Authority Province-wide solutions.

Collected on: Aug 22 2022 08:36 Received on: Aug 23 2022 08:30 Reported on: Aug 24 2022 13:46

Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2022-08-26 08:36

Page 1 of 1

BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Flag Result

Reference Range - Units

Sample: GIBSONS WATER SYSTEM

Test

SITE 13 PARKLAND RESERVOIR SAMPLE PORT LOW

## **Environmental Report**

Reported to:

**Environmental Water Samplings** 

Sample Type Drinking water Method Membrane Filtration **Environmental Health Officer** Darren Molder Site Address Parkland | System Type WS1A Specimen Source Deep Well

Site Treatment No



Reported by: PHSA Environmental

Reference Range - Units

Provincial Health Services Authority Province-wide solutions.

Collected on: Aug 22 2022 09:28 Received on: Aug 23 2022 08:30 Reported on: Aug 24 2022 13:46

Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2022-08-26 08:36 BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Flag Result

Page 1 of 1

Sample: GIBSONS WATER SYSTEM

SITE 14 DAVIS ROAD

Test

## **Environmental Report**

Reported to:

**Environmental Water Samplings** 

Drinking water Sample Type Method Membrane Filtration **Environmental Health Officer** Darren Molder Site Address Davis Road System Type WS1A Specimen Source Deep Well

Site Treatment No



Reported by: PHSA Environmental

Provincial Health
Services Authority
Province-wide solutions.
Better health.

Collected on: Aug 22 2022 10:49
Received on: Aug 23 2022 08:30
Reported on: Aug 24 2022 13:49

Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2022-08-26 08:36

Page 1 of 1

Reference Range - Units

BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Test Flag Result

Sample: GIBSONS WATER SYSTEM SITE 15 ARBUTUS REACH

Environmental Report

Reported to:

**Environmental Water Samplings** 

Sample Type Drinking water
Method Membrane Filtration
Environmental Health Officer Darren Molder
Site Address Arbutus Reach

System Type WS1A
Specimen Source Deep Well

Site Treatment No



Count/100mL

Count/100mL

Reported by: PHSA Environmental

Provincial Health Services Authority Province-wide solutions.

Collected on: Aug 22 2022 08:59 Received on: Aug 23 2022 08:30 Reported on: Aug 24 2022 13:46

Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2022-08-26 08:36 BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Page 1 of 1

Test Flag Result Reference Range - Units

Sample: GIBSONS WATER SYSTEM

SITE 2 PARK ROAD

# **Environmental Report**

Reported to:

**Environmental Water Samplings** 

Drinking water Sample Type Method Membrane Filtration **Environmental Health Officer** Darren Molder Site Address Park Road System Type WS1A Specimen Source Combined Site Treatment Yes

**Total Coliform** Less than 1 Escherichia Coli Less than 1

FINAL RESULTS



Reported by: PHSA Environmental

Provincial Health Services Authority Province-wide solutions.

Collected on: Aug 22 2022 09:10 Received on: Aug 23 2022 08:30 Reported on: Aug 24 2022 13:49

Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2022-08-26 08:36

Page 1 of 1

BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT) Flag Result

Reference Range - Units

Sample: GIBSONS WATER SYSTEM

Test

SITE 4 KIWANIS

## **Environmental Report**

Reported to:

**Environmental Water Samplings** 

Drinking water Sample Type Method Membrane Filtration **Environmental Health Officer** Darren Molder Site Address Upper Gibsons

WS1A System Type Specimen Source Combined Site Treatment Yes



Reported by: PHSA Environmental

Provincial Health Services Authority Province-wide solutions.

Collected on: Aug 22 2022 09:19 Received on: Aug 23 2022 08:30 Reported on: Aug 24 2022 13:49

VANCOUVER COASTAL HEALTH (SECHELT)

Ordered by: Reported to:

Printed on: 2022-08-26 08:36 BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT) Page 1 of 1

Test Flag Result Reference Range - Units

Sample: GIBSONS WATER SYSTEM

SITE 5 GIBSONS WAY

## **Environmental Report**

**Environmental Water Samplings** 

Drinking water Sample Type Method Membrane Filtration **Environmental Health Officer** Darren Molder Site Address Highway 101 WS1A System Type Specimen Source Combined Site Treatment Yes



Reported by: PHSA Environmental

Reference Range - Units

Provincial Health
Services Authority
Province-vide solutions.
Better health.

Collected on: Aug 22 2022 09:35 Received on: Aug 23 2022 08:30 Reported on: Aug 24 2022 13:46

Flag Result

Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2022-08-26 08:36

BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT) Page 1 of 1

Sample: GIBSONS WATER SYSTEM

SITE 6 SHAW ROAD

Test

## **Environmental Report**

Reported to:

**Environmental Water Samplings** 

Sample Type Drinking water
Method Membrane Filtration
Environmental Health Officer Darren Molder
Site Address Shaw Road
System Type WS1A
Specimen Source Deep Well

Site Treatment No



Reported by: PHSA Environmental

Reference Range - Units

Provincial Health Services Authority Province-wide solutions.

Collected on: Aug 22 2022 10:59 Received on: Aug 23 2022 08:30 Reported on: Aug 24 2022 13:46

Flag Result

Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2022-08-26 08:36 BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Page 1 of 1

Sample: GIBSONS WATER SYSTEM

Test

SITE 7 ABBS ROAD

# **Environmental Report**

Reported to:

**Environmental Water Samplings** 

Drinking water Sample Type Method Membrane Filtration **Environmental Health Officer** Darren Molder Site Address Abbs Road System Type WS1A Specimen Source Deep Well

Site Treatment No



Reported by: PHSA Environmental

Provincial Health Services Authority Province-wide solutions.

Collected on: Aug 22 2022 10:41 Received on: Aug 23 2022 08:30 Reported on: Aug 24 2022 13:46

Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2022-08-26 08:36 BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Page 1 of 1

Test Flag Result Reference Range - Units

Sample: GIBSONS WATER SYSTEM SITE 8 FRANKLIN ROAD

# **Environmental Report**

Reported to:

**Environmental Water Samplings** 

Drinking water Sample Type Method Membrane Filtration **Environmental Health Officer** Darren Molder Site Address Franklin Road System Type WS1A

Specimen Source Deep Well Site Treatment No



Reported by: PHSA Environmental

Provincial Health Services Authority Province-wide solutions.

Collected on: Aug 22 2022 11:10 Received on: Aug 23 2022 08:30 Reported on: Aug 24 2022 13:46

Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2022-08-26 08:36 BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Page 1 of 1

Test Flag Result Reference Range - Units

Sample: GIBSONS WATER SYSTEM

SITE 9 BALLS LANE

# **Environmental Report**

Reported to:

**Environmental Water Samplings** 

Drinking water Sample Type Method Membrane Filtration **Environmental Health Officer** Darren Molder Site Address Balls Lane System Type WS1A Specimen Source Deep Well

Site Treatment No



Reported by: PHSA Environmental

Provincial Health Services Authority Province-wide solutions.

Collected on: Aug 22 2022 10:45 Received on: Aug 23 2022 08:30 Reported on: Aug 24 2022 13:49

Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2022-08-26 08:36 BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Page 1 of 1

Test Flag Result Reference Range - Units

Sample: GIBSONS WATER SYSTEM

WELL 1

## **Environmental Report**

Reported to:

**Environmental Water Samplings** 

Drinking water Sample Type Method Membrane Filtration **Environmental Health Officer** Darren Molder Gower Point Road Site Address

System Type WS1A Specimen Source Deep Well

Site Treatment No



Printed on: 2022-08-26 08:36

Reference Range - Units

Reported by: PHSA Environmental

Provincial Health Services Authority Province-wide solutions.

Collected on: Aug 22 2022 10:24 Received on: Aug 23 2022 08:30 Reported on: Aug 24 2022 13:49

Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Flag Result

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Page 1 of 1

Sample: GIBSONS WATER SYSTEM

Test

WELL 3

## **Environmental Report**

**Environmental Water Samplings** 

Drinking water Sample Type Method Membrane Filtration **Environmental Health Officer** Darren Molder

Winn T Gower Point Road Site Address

System Type WS1A Specimen Source Deep Well

Site Treatment No



Reported by: PHSA Environmental

Provincial Health
Services Authority
Province-vide solutions.
Better health.

Collected on: Aug 22 2022 11:19 Received on: Aug 23 2022 08:30 Reported on: Aug 24 2022 13:49

Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2022-08-26 08:36

Page 1 of 1

BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Test Flag Result Refe

Reference Range - Units

Sample: GIBSONS WATER SYSTEM

WELL 4

## **Environmental Report**

Reported to:

**Environmental Water Samplings** 

Sample Type Drinking water
Method Membrane Filtration
Environmental Health Officer Darren Molder
Site Address Gower Point Road

System Type WS1A
Specimen Source Deep Well

Site Treatment No