

Reported by: PHSA Environmental

Collected on: Oct 05 2022 09:05

Received on: Oct 06 2022 08:30

Reported on: Oct 07 2022 10:01



Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2022-10-11 09:18

Page 1 of 1

Test	Flag Result	Reference Range - Units
------	-------------	-------------------------

Sample: GIBSONS WATER SYSTEM
SITE 10 SCHOOL ROAD RESERVOIR

Environmental Report

Environmental Water Samplings

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	School Road	
System Type	WS1A	
Specimen Source	Deep Well	
Site Treatment	No	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental



Collected on: Oct 05 2022 09:20

Received on: Oct 06 2022 08:30

Reported on: Oct 07 2022 10:01

Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2022-10-11 09:18

Page 1 of 1

Test	Flag Result	Reference Range - Units
------	-------------	-------------------------

Sample: GIBSONS WATER SYSTEM
 SITE 13 PARKLAND RESERVOIR SAMPLE PORT LOW

Environmental Report

Environmental Water Samplings

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	Parkland	
System Type	WS1A	
Specimen Source	Deep Well	
Site Treatment	No	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental

Collected on: Oct 05 2022 09:30

Received on: Oct 06 2022 08:30

Reported on: Oct 07 2022 10:01



Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2022-10-11 09:18

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Page 1 of 1

Test	Flag Result	Reference Range - Units
------	-------------	-------------------------

Sample: GIBSONS WATER SYSTEM
SITE 6 SHAW ROAD

Environmental Report

Environmental Water Samplings

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	Shaw Road	
System Type	WS1A	
Specimen Source	Deep Well	
Site Treatment	No	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental

Collected on: Oct 05 2022 08:40

Received on: Oct 06 2022 08:30

Reported on: Oct 07 2022 10:01



Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2022-10-11 09:18

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Page 1 of 1

Test	Flag Result	Reference Range - Units
------	-------------	-------------------------

Sample: GIBSONS WATER SYSTEM
SITE 8 FRANKLIN ROAD

Environmental Report

Environmental Water Samplings

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	Franklin Road	
System Type	WS1A	
Specimen Source	Deep Well	
Site Treatment	No	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental

Collected on: Oct 05 2022 08:45

Received on: Oct 06 2022 08:30

Reported on: Oct 07 2022 10:01



Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2022-10-11 09:18

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Page 1 of 1

Test	Flag Result	Reference Range - Units
------	-------------	-------------------------

Sample: GIBSONS WATER SYSTEM
SITE 9 BALLS LANE

Environmental Report

Environmental Water Samplings

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	Balls Lane	
System Type	WS1A	
Specimen Source	Deep Well	
Site Treatment	No	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental



Collected on: Oct 13 2022 09:46

Received on: Oct 14 2022 08:30

Reported on: Oct 15 2022 10:46

Printed on: 2022-10-17 10:34
Page 1 of 1

Order by: VANCOUVER COASTAL HEALTH (SECHLT)
Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHLT)

Test Flag Result Reference Range - Units

Sample: GIBSONS WATER SYSTEM
SITE 2 PARK ROAD

Environmental Report

Environmental Water Samplings

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	Park Road	
System Type	WS1A	
Specimen Source	Combined	
Site Treatment	Yes	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental



Collected on: Oct 13 2022 09:54
Received on: Oct 14 2022 08:30
Reported on: Oct 15 2022 10:46

Printed on: 2022-10-17 10:34
Page 1 of 1

Order by: VANCOUVER COASTAL HEALTH (SECHLT)
Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHLT)
Test Flag Result

Reference Range - Units

Sample: GIBSONS WATER SYSTEM
SITE 4 KIWANIS

Environmental Report

Environmental Water Samplings

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	Upper Gibsons	
System Type	WS1A	
Specimen Source	Combined	
Site Treatment	Yes	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental



Collected on: Oct 13 2022 10:10
Received on: Oct 14 2022 08:30
Reported on: Oct 15 2022 10:46

Printed on: 2022-10-17 10:34
Page 1 of 1

Order by: VANCOUVER COASTAL HEALTH (SECHELT)
Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)
Test Flag Result

Reference Range - Units

Sample: GIBSONS WATER SYSTEM
SITE 14 DAVIS ROAD

Environmental Report

Environmental Water Samplings

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	Davis Road	
System Type	WS1A	
Specimen Source	Deep Well	
Site Treatment	No	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental



Collected on: Oct 13 2022 09:34

Received on: Oct 14 2022 08:30

Reported on: Oct 15 2022 10:46

Order by: VANCOUVER COASTAL HEALTH (SECHLT)
 Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHLT)

Printed on: 2022-10-17 10:34
 Page 1 of 1

Test

Flag Result

Reference Range - Units

Sample: GIBSONS WATER SYSTEM
 SITE 13 PARKLAND RESERVOIR SAMPLE PORT LOW

Environmental Report

Environmental Water Samplings

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	Parkland	
System Type	WS1A	
Specimen Source	Deep Well	
Site Treatment	No	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental



Collected on: Oct 13 2022 10:01

Received on: Oct 14 2022 08:30

Reported on: Oct 15 2022 10:46

Order by: VANCOUVER COASTAL HEALTH (SECHLT)
 Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHLT)

Printed on: 2022-10-17 10:34
 Page 1 of 1

Test	Flag	Result	Reference Range - Units
------	------	--------	-------------------------

Sample: GIBSONS WATER SYSTEM
 SITE 5 GIBSONS WAY

Environmental Report

Environmental Water Samplings

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	Highway 101	
System Type	WS1A	
Specimen Source	Combined	
Site Treatment	Yes	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental



Collected on: Oct 13 2022 10:41
 Received on: Oct 14 2022 08:30
 Reported on: Oct 15 2022 10:46

Printed on: 2022-10-17 10:34
 Page 1 of 1

Order by: VANCOUVER COASTAL HEALTH (SECHLT)
 Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHLT)
 Test Flag Result

Reference Range - Units

Sample: GIBSONS WATER SYSTEM
 SITE 8 FRANKLIN ROAD

Environmental Report

Environmental Water Samplings

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	Franklin Road	
System Type	WS1A	
Specimen Source	Deep Well	
Site Treatment	No	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental



Collected on: Oct 13 2022 10:46
Received on: Oct 14 2022 08:30
Reported on: Oct 15 2022 10:46

Printed on: 2022-10-17 10:34
Page 1 of 1

Order by: VANCOUVER COASTAL HEALTH (SECHLT)
Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHLT)
Test

Reference Range - Units

Sample: GIBSONS WATER SYSTEM
SITE 15 ARBUTUS REACH

Environmental Report

Environmental Water Samplings

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	Arbutus Reach	
System Type	WS1A	
Specimen Source	Deep Well	
Site Treatment	No	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental



Collected on: Oct 13 2022 10:22
Received on: Oct 14 2022 08:30
Reported on: Oct 15 2022 10:46

Printed on: 2022-10-17 10:34
Page 1 of 1

Order by: VANCOUVER COASTAL HEALTH (SECHLT)
Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHLT)
Test Flag Result

Reference Range - Units

Sample: GIBSONS WATER SYSTEM
SITE 10 SCHOOL ROAD RESERVOIR

Environmental Report

Environmental Water Samplings

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	School Road	
System Type	WS1A	
Specimen Source	Deep Well	
Site Treatment	No	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental



Collected on: Oct 13 2022 10:16

Received on: Oct 14 2022 08:30

Reported on: Oct 15 2022 10:46

Order by: VANCOUVER COASTAL HEALTH (SECHLT)
 Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHLT)

Printed on: 2022-10-17 10:34
 Page 1 of 1

Test	Flag	Result	Reference Range - Units
------	------	--------	-------------------------

Sample: GIBSONS WATER SYSTEM
 SITE 6 SHAW ROAD

Environmental Report

Environmental Water Samplings

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	Shaw Road	
System Type	WS1A	
Specimen Source	Deep Well	
Site Treatment	No	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental



Collected on: Oct 13 2022 10:32

Received on: Oct 14 2022 08:30

Reported on: Oct 15 2022 10:46

Printed on: 2022-10-17 10:34
Page 1 of 1

Order by: VANCOUVER COASTAL HEALTH (SECHLT)
Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHLT)
Test Flag Result

Reference Range - Units

Sample: GIBSONS WATER SYSTEM
SITE 7 ABBS ROAD

Environmental Report

Environmental Water Samplings

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	Abbs Road	
System Type	WS1A	
Specimen Source	Deep Well	
Site Treatment	No	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental

Collected on: Oct 19 2022 07:24

Received on: Oct 20 2022 08:30

Reported on: Oct 21 2022 13:03



Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2022-10-24 09:14

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Page 1 of 1

Test	Flag Result	Reference Range - Units
------	-------------	-------------------------

Sample: GIBSONS WATER SYSTEM
SITE 10 SCHOOL ROAD RESERVOIR

Environmental Report

Environmental Water Samplings

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	School Road	
System Type	WS1A	
Specimen Source	Deep Well	
Site Treatment	No	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental

Collected on: Oct 19 2022 07:01

Received on: Oct 20 2022 08:30

Reported on: Oct 21 2022 13:03



Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2022-10-24 09:14

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Page 1 of 1

Test	Flag Result	Reference Range - Units
------	-------------	-------------------------

Sample: GIBSONS WATER SYSTEM
SITE 13 PARKLAND RESERVOIR SAMPLE PORT LOW

Environmental Report

Environmental Water Samplings

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	Parkland	
System Type	WS1A	
Specimen Source	Deep Well	
Site Treatment	No	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental

Collected on: Oct 19 2022 07:16

Received on: Oct 20 2022 08:30

Reported on: Oct 21 2022 13:03



Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2022-10-24 09:14

Page 1 of 1

Test	Flag Result	Reference Range - Units
------	-------------	-------------------------

Sample: GIBSONS WATER SYSTEM
SITE 6 SHAW ROAD

Environmental Report

Environmental Water Samplings

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	Shaw Road	
System Type	WS1A	
Specimen Source	Deep Well	
Site Treatment	No	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental



Collected on: Oct 19 2022 07:41
 Received on: Oct 20 2022 08:30
 Reported on: Oct 21 2022 13:03

Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)
 Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2022-10-24 09:14
 Page 1 of 1

Test	Flag Result	Reference Range - Units
------	-------------	-------------------------

Sample: GIBSONS WATER SYSTEM
 SITE 8 FRANKLIN ROAD

Environmental Report

Environmental Water Samplings

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	Franklin Road	
System Type	WS1A	
Specimen Source	Deep Well	
Site Treatment	No	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental

Collected on: Oct 19 2022 07:33

Received on: Oct 20 2022 08:30

Reported on: Oct 21 2022 13:03



Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2022-10-24 09:14

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Page 1 of 1

Test	Flag Result	Reference Range - Units
------	-------------	-------------------------

Sample: GIBSONS WATER SYSTEM
SITE 9 BALLS LANE

Environmental Report

Environmental Water Samplings

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	Balls Lane	
System Type	WS1A	
Specimen Source	Deep Well	
Site Treatment	No	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL



Collected on: Oct 26 2022 09:59

Received on: Oct 27 2022 08:30

Reported on: Oct 28 2022 10:08

Ordered by: VANCOUVER COASTAL HEALTH (SECHLT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHLT)

Printed on: 2022-10-31 08:40

Page 1 of 1

Test	Flag	Result	Reference Range - Units
------	------	--------	-------------------------

Sample: GIBSONS WATER SYSTEM
SITE 4 KIWANIS

Environmental Report

Environmental Water Samplings

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	Upper Gibsons	
System Type	WS1A	
Specimen Source	Combined	
Site Treatment	Yes	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental



Collected on: Oct 26 2022 10:11

Received on: Oct 27 2022 08:30

Reported on: Oct 28 2022 10:08

Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2022-10-31 08:40

Page 1 of 1

Test	Flag	Result	Reference Range - Units
------	------	--------	-------------------------

Sample: GIBSONS WATER SYSTEM
SITE 6 SHAW ROAD

Environmental Report

Environmental Water Samplings

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	Shaw Road	
System Type	WS1A	
Specimen Source	Deep Well	
Site Treatment	No	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental



Collected on: Oct 26 2022 09:19

Received on: Oct 27 2022 08:30

Reported on: Oct 28 2022 10:08

Ordered by: VANCOUVER COASTAL HEALTH (SECHLT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHLT)

Printed on: 2022-10-31 08:40

Page 1 of 1

Test	Flag	Result	Reference Range - Units
------	------	--------	-------------------------

Sample: GIBSONS WATER SYSTEM
WELL 4

Environmental Report

Environmental Water Samplings

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	Gower Point Road	
System Type	WS1A	
Specimen Source	Deep Well	
Site Treatment	No	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental



Collected on: Oct 26 2022 09:04

Received on: Oct 27 2022 08:30

Reported on: Oct 28 2022 10:08

Ordered by: VANCOUVER COASTAL HEALTH (SECHLT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHLT)

Printed on: 2022-10-31 08:40

Page 1 of 1

Test	Flag	Result	Reference Range - Units
------	------	--------	-------------------------

Sample: GIBSONS WATER SYSTEM
WELL 3

Environmental Report

Environmental Water Samplings

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	Winn T Gower Point Road	
System Type	WS1A	
Specimen Source	Deep Well	
Site Treatment	No	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental



Collected on: Oct 26 2022 10:04

Received on: Oct 27 2022 08:30

Reported on: Oct 28 2022 10:08

Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2022-10-31 08:40

Page 1 of 1

Test	Flag	Result	Reference Range - Units
------	------	--------	-------------------------

Sample: GIBSONS WATER SYSTEM
SITE 14 DAVIS ROAD

Environmental Report

Environmental Water Samplings

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	Davis Road	
System Type	WS1A	
Specimen Source	Deep Well	
Site Treatment	No	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental



Collected on: Oct 26 2022 10:18

Received on: Oct 27 2022 08:30

Reported on: Oct 28 2022 10:08

Ordered by: VANCOUVER COASTAL HEALTH (SECHLT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHLT)

Printed on: 2022-10-31 08:40

Page 1 of 1

Test	Flag	Result	Reference Range - Units
------	------	--------	-------------------------

Sample: GIBSONS WATER SYSTEM
SITE 2 PARK ROAD

Environmental Report

Environmental Water Samplings

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	Park Road	
System Type	WS1A	
Specimen Source	Combined	
Site Treatment	Yes	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental



Collected on: Oct 26 2022 08:49

Received on: Oct 27 2022 08:30

Reported on: Oct 28 2022 10:07

Ordered by: VANCOUVER COASTAL HEALTH (SECHLT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHLT)

Printed on: 2022-10-31 08:40

Page 1 of 1

Test	Flag	Result	Reference Range - Units
------	------	--------	-------------------------

Sample: GIBSONS WATER SYSTEM
SITE 8 FRANKLIN ROAD

Environmental Report

Environmental Water Samplings

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	Franklin Road	
System Type	WS1A	
Specimen Source	Deep Well	
Site Treatment	No	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental



Collected on: Oct 26 2022 09:35

Received on: Oct 27 2022 08:30

Reported on: Oct 28 2022 10:07

Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2022-10-31 08:40

Page 1 of 1

Test	Flag	Result	Reference Range - Units
------	------	--------	-------------------------

Sample: GIBSONS WATER SYSTEM
SITE 7 ABBS ROAD

Environmental Report

Environmental Water Samplings

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	Abbs Road	
System Type	WS1A	
Specimen Source	Deep Well	
Site Treatment	No	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental



Collected on: Oct 26 2022 09:11

Received on: Oct 27 2022 08:30

Reported on: Oct 28 2022 10:07

Ordered by: VANCOUVER COASTAL HEALTH (SECHLT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHLT)

Printed on: 2022-10-31 08:40

Page 1 of 1

Test	Flag	Result	Reference Range - Units
------	------	--------	-------------------------

Sample: GIBSONS WATER SYSTEM
WELL 1

Environmental Report

Environmental Water Samplings

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	Gower Point Road	
System Type	WS1A	
Specimen Source	Deep Well	
Site Treatment	No	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental



Collected on: Oct 26 2022 08:55

Received on: Oct 27 2022 08:30

Reported on: Oct 28 2022 10:07

Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2022-10-31 08:40

Page 1 of 1

Test	Flag	Result	Reference Range - Units
------	------	--------	-------------------------

Sample: GIBSONS WATER SYSTEM
SITE 15 ARBUTUS REACH

Environmental Report

Environmental Water Samplings

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	Arbutus Reach	
System Type	WS1A	
Specimen Source	Deep Well	
Site Treatment	No	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental



Collected on: Oct 26 2022 09:26

Received on: Oct 27 2022 08:30

Reported on: Oct 28 2022 10:07

Ordered by: VANCOUVER COASTAL HEALTH (SECHLT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHLT)

Printed on: 2022-10-31 08:40

Page 1 of 1

Test	Flag	Result	Reference Range - Units
------	------	--------	-------------------------

Sample: GIBSONS WATER SYSTEM
SITE 9 BALLS LANE

Environmental Report

Environmental Water Samplings

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	Balls Lane	
System Type	WS1A	
Specimen Source	Deep Well	
Site Treatment	No	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental



Collected on: Oct 26 2022 09:49

Received on: Oct 27 2022 08:30

Reported on: Oct 28 2022 10:07

Ordered by: VANCOUVER COASTAL HEALTH (SECHLT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHLT)

Printed on: 2022-10-31 08:40

Page 1 of 1

Test	Flag	Result	Reference Range - Units
------	------	--------	-------------------------

Sample: GIBSONS WATER SYSTEM
SITE 5 GIBSONS WAY

Environmental Report

Environmental Water Samplings

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	Highway 101	
System Type	WS1A	
Specimen Source	Combined	
Site Treatment	Yes	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental



Collected on: Oct 26 2022 09:41

Received on: Oct 27 2022 08:30

Reported on: Oct 28 2022 10:07

Ordered by: VANCOUVER COASTAL HEALTH (SECHLT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHLT)

Printed on: 2022-10-31 08:40

Page 1 of 1

Test	Flag	Result	Reference Range - Units
------	------	--------	-------------------------

Sample: GIBSONS WATER SYSTEM
SITE 10 SCHOOL ROAD RESERVOIR

Environmental Report

Environmental Water Samplings

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	School Road	
System Type	WS1A	
Specimen Source	Deep Well	
Site Treatment	No	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental



Collected on: Oct 26 2022 10:31

Received on: Oct 27 2022 08:30

Reported on: Oct 28 2022 10:07

Ordered by: VANCOUVER COASTAL HEALTH (SECHLT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHLT)

Printed on: 2022-10-31 08:40

Page 1 of 1

Test	Flag	Result	Reference Range - Units
------	------	--------	-------------------------

Sample: GIBSONS WATER SYSTEM
SITE 13 PARKLAND RESERVOIR SAMPLE PORT LOW

Environmental Report

Environmental Water Samplings

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	Parkland	
System Type	WS1A	
Specimen Source	Deep Well	
Site Treatment	No	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL