

Reported by: PHSA Environmental

Provincial Health
Services Authority
Province-wide solutions.
Better health.

Collected on: Nov 01 2022 10:44
Received on: Nov 02 2022 08:30
Reported on: Nov 03 2022 15:27

Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2022-11-04 08:26

Page 1 of 1

BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Flag Result

Reference Range - Units

Sample: GIBSONS WATER SYSTEM

SITE 10 SCHOOL ROAD RESERVOIR

Test

Environmental Report

Reported to:

Environmental Water Samplings

Sample Type Drinking water
Method Membrane Filtration
Environmental Health Officer Darren Molder
Site Address School Road
System Type WS1A
Specimen Source Deep Well

Site Treatment No



Reported by: PHSA Environmental

Collected on: Nov 01 2022 10:59

Received on: Nov 02 2022 08:30

Reported on: Nov 03 2023 15:27

Received on: Nov 02 2022 08:30 Reported on: Nov 03 2022 15:27

Ordered by: VANCOUVER COASTAL HEALTH (SECHELT) Printed on: 2022-11-04 08:26

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT) Page 1 of 1

Test Flag Result Reference Range - Units

Sample: GIBSONS WATER SYSTEM

SITE 13 PARKLAND RESERVOIR SAMPLE PORT LOW

Environmental Report

Environmental Water Samplings

Sample Type Drinking water
Method Membrane Filtration
Environmental Health Officer Darren Molder
Site Address Parkland
System Type WS1A
Specimen Source Deep Well

Site Treatment No

Laboratory Comment Query date of collection given.



Reported by: PHSA Environmental

Provincial Health
Services Authority
Province vide solutions.
Better health.

Collected on: Nov 01 2022 10:51
Received on: Nov 02 2022 08:30
Reported on: Nov 03 2022 15:27

Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2022-11-04 08:26

Page 1 of 1

BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Flag Result

Reference Range - Units

Sample: GIBSONS WATER SYSTEM

SITE 6 SHAW ROAD

Test

Environmental Report

Reported to:

Environmental Water Samplings

Sample Type Drinking water
Method Membrane Filtration
Environmental Health Officer Darren Molder
Site Address Shaw Road
System Type WS1A
Specimen Source Deep Well

Site Treatment No

Laboratory Comment Query date of collection given.



Reported by: PHSA Environmental

Provincial Health Services Authority Province-wide solutions.

Collected on: Nov 01 2022 10:27 Received on: Nov 02 2022 08:30 Reported on: Nov 03 2022 15:27

Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2022-11-04 08:26

Page 1 of 1

Reference Range - Units

BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT) Flag Result

Sample: GIBSONS WATER SYSTEM

SITE 8 FRANKLIN ROAD

Test

Environmental Report

Reported to:

Environmental Water Samplings

Sample Type Drinking water Method Membrane Filtration **Environmental Health Officer** Darren Molder Site Address Franklin Road WS1A System Type

Specimen Source Deep Well Site Treatment No

Laboratory Comment Query date of collection given.

Lab No: T2262853



Reported by: PHSA Environmental

Province-wide solutions.

Provincial Health Collected on: Nov 01 2022 10:36 Services Authority Received on: Nov 02 2022 08:30 Reported on: Nov 03 2022 15:27

Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2022-11-04 08:26

Page 1 of 1

BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Flag Result

Reference Range - Units

Sample: GIBSONS WATER SYSTEM

Test

SITE 9 BALLS LANE

Environmental Report

Reported to:

Environmental Water Samplings

Sample Type Drinking water Method Membrane Filtration **Environmental Health Officer** Darren Molder Site Address Balls Lane System Type WS1A Specimen Source Deep Well

Site Treatment No

Laboratory Comment Query date of collection given.



Reported by: PHSA Environmental

Provincial Health Services Authority Province-wide solutions.

Collected on: Nov 09 2022 09:56 Received on: Nov 10 2022 08:30 Reported on: Nov 11 2022 12:25

Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2022-11-14 08:13

Page 1 of 1

BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT) Test Flag Result Reference Range - Units

Sample: GIBSONS WATER SYSTEM

SITE 10 SCHOOL ROAD RESERVOIR

Environmental Report

Reported to:

Environmental Water Samplings

Sample Type Drinking water Method Membrane Filtration **Environmental Health Officer** Darren Molder Site Address School Road WS1A System Type Specimen Source Deep Well

Site Treatment No



Reported by: PHSA Environmental

Reference Range - Units

Collected on: Nov 09 2022 09:19 Received on: Nov 10 2022 08:30 Reported on: Nov 11 2022 12:25

Provincial Health Services Authority Province-wide solutions.

Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2022-11-14 08:13 BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Page 1 of 1

Flag Result

Sample: GIBSONS WATER SYSTEM

Test

SITE 13 PARKLAND RESERVOIR SAMPLE PORT LOW

Environmental Report

Reported to:

Environmental Water Samplings

Sample Type Drinking water Method Membrane Filtration **Environmental Health Officer** Darren Molder Site Address Parkland WS1A System Type Specimen Source Deep Well

Site Treatment No



Reported by: PHSA Environmental

Provincial Health
Services Authority
Province-vide solutions.
Better health.

Collected on: Nov 09 2022 09:41 Received on: Nov 10 2022 08:30 Reported on: Nov 11 2022 12:16

Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2022-11-14 08:13

Page 1 of 1

BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Flag Result

Reference Range - Units

Sample: GIBSONS WATER SYSTEM

SITE 14 DAVIS ROAD

Test

Environmental Report

Reported to:

Environmental Water Samplings

Sample Type Drinking water
Method Membrane Filtration
Environmental Health Officer Darren Molder
Site Address Davis Road
System Type WS1A
Specimen Source Deep Well

Site Treatment No



Reported by: PHSA Environmental

Provincial Health Services Authority Province-wide solutions.

Collected on: Nov 09 2022 10:34 Received on: Nov 10 2022 08:30 Reported on: Nov 11 2022 12:16

Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2022-11-14 08:13 BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Page 1 of 1

Test Flag Result Reference Range - Units

Sample: GIBSONS WATER SYSTEM SITE 15 ARBUTUS REACH

Environmental Report

Reported to:

Environmental Water Samplings

Sample Type Drinking water Method Membrane Filtration **Environmental Health Officer** Darren Molder Site Address Arbutus Reach

WS1A System Type Specimen Source Deep Well Site Treatment No

BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)



Reported by: PHSA Environmental

Provincial Health
Services Authority
Province-wide solutions.
Better health.

Collected on: Nov 09 2022 09:07 Received on: Nov 10 2022 08:30

Reported on: Nov 11 2022 12:25

Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2022-11-14 08:13

Page 1 of 1

Test Flag Result Reference Range - Units

Sample: GIBSONS WATER SYSTEM

SITE 2 PARK ROAD

Environmental Report

Reported to:

Environmental Water Samplings

Sample Type Drinking water
Method Membrane Filtration
Environmental Health Officer Darren Molder
Site Address Park Road
System Type WS1A
Specimen Source Combined
Site Treatment Yes



Reported by: PHSA Environmental

Provincial Health
Services Authority
Province-vide solutions.
Batter health

Collected on: Nov 09 2022 10:11 Received on: Nov 10 2022 08:30 Reported on: Nov 11 2022 12:25

Flag Result

Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2022-11-14 08:13

Page 1 of 1

BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Reference Range - Units

Sample: GIBSONS WATER SYSTEM

Test

SITE 4 KIWANIS

Environmental Report

Reported to:

Environmental Water Samplings

Sample Type Drinking water
Method Membrane Filtration
Environmental Health Officer Darren Molder
Site Address Upper Gibsons

System Type WS1A
Specimen Source Combined
Site Treatment Yes



Reported by: PHSA Environmental

Reference Range - Units

Provincial Health
Services Authority
Province-wide solutions.
Better health.

Collected on: Nov 09 2022 10:04 Received on: Nov 10 2022 08:30 Reported on: Nov 11 2022 12:25

Flag Result

Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2022-11-14 08:13

BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT) Page 1 of 1

Sample: GIBSONS WATER SYSTEM

SITE 5 GIBSONS WAY

Test

Environmental Report

Reported to:

Environmental Water Samplings

Sample Type Drinking water
Method Membrane Filtration
Environmental Health Officer Darren Molder
Site Address Highway 101
System Type WS1A
Specimen Source Combined
Site Treatment Yes



Reported by: PHSA Environmental

Reference Range - Units

Provincial Health Services Authority Province-wide solutions.

Collected on: Nov 09 2022 09:49 Received on: Nov 10 2022 08:30 Reported on: Nov 11 2022 12:25

Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2022-11-14 08:13 BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Flag Result

Page 1 of 1

Sample: GIBSONS WATER SYSTEM

Test

SITE 6 SHAW ROAD

Environmental Report

Reported to:

Environmental Water Samplings

Sample Type Drinking water Method Membrane Filtration **Environmental Health Officer** Darren Molder Site Address Shaw Road WS1A System Type Specimen Source Deep Well

Site Treatment No

Flag Result



Reported by: PHSA Environmental

Collected on: Nov 09 2022 10:21

Received on: Nov 10 2022 08:30

Reported on: Nov 11 2022 12:16

Provincial Health
Services Authority
Province-wide solutions.
Better health.

Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2022-11-14 08:13

Page 1 of 1

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Reference Range - Units

Sample: GIBSONS WATER SYSTEM

Test

SITE 7 ABBS ROAD

Environmental Report

Environmental Water Samplings

Sample Type Drinking water
Method Membrane Filtration
Environmental Health Officer Darren Molder
Site Address Abbs Road
System Type WS1A
Specimen Source Deep Well

Site Treatment No



Reported by: PHSA Environmental

Provincial Health Services Authority Province-wide solutions.

Collected on: Nov 09 2022 10:28 Received on: Nov 10 2022 08:30 Reported on: Nov 11 2022 12:16

Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2022-11-14 08:13

Page 1 of 1

BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT) Flag Result

Reference Range - Units

Sample: GIBSONS WATER SYSTEM SITE 8 FRANKLIN ROAD

Test

Environmental Report

Reported to:

Environmental Water Samplings

Sample Type Drinking water Method Membrane Filtration **Environmental Health Officer** Darren Molder Site Address Franklin Road WS1A System Type

Specimen Source Deep Well Site Treatment No



Reported by: PHSA Environmental

Provincial Health
Services Authority
Province-wide solutions.
Better health.

Collected on: Nov 09 2022 10:44 Received on: Nov 10 2022 08:30 Reported on: Nov 11 2022 12:25

Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2022-11-14 08:13

Page 1 of 1

BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Test Flag Result

Reference Range - Units

Sample: GIBSONS WATER SYSTEM

SITE 9 BALLS LANE

Environmental Report

Reported to:

Environmental Water Samplings

Sample Type Drinking water
Method Membrane Filtration
Environmental Health Officer Darren Molder
Site Address Balls Lane
System Type WS1A
Specimen Source Deep Well

Site Treatment No



Reported by: PHSA Environmental

Provincial Health Services Authority Province-wide solutions. Better health.

Collected on: Nov 14 2022 10:11 Received on: Nov 15 2022 08:30 Reported on: Nov 16 2022 12:48

Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2022-11-17 08:28

Page 1 of 1

BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Flag Result

Reference Range - Units

Sample: GIBSONS WATER SYSTEM

SITE 10 SCHOOL ROAD RESERVOIR

Test

Environmental Report

Reported to:

Environmental Water Samplings

Sample Type Drinking water
Method Membrane Filtration
Environmental Health Officer Darren Molder
Site Address School Road
System Type WS1A
Specimen Source Deep Well
Site Treatment No

Total Coliform Less than 1
Escherichia Coli Less than 1

Count/100mL Count/100mL



Reported by: PHSA Environmental

Provincial Health
Services Authority
Province wide solutions.
Beter health.

Collected on: Nov 14 2022 09:36 Received on: Nov 15 2022 08:30 Reported on: Nov 16 2022 13:00

Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2022-11-17 08:28

Page 1 of 1

BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Flag Result

Reference Range - Units

Sample: GIBSONS WATER SYSTEM

Test

SITE 13 PARKLAND RESERVOIR SAMPLE PORT LOW

Environmental Report

Reported to:

Environmental Water Samplings

Sample Type Drinking water
Method Membrane Filtration
Environmental Health Officer Darren Molder
Site Address Parkland
System Type WS1A
Specimen Source Deep Well

Site Treatment No

BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)



Reported by: PHSA Environmental

Collected on: Nov 14 2022 10:04

Received on: Nov 15 2022 08:30

Provincial Health Services Authority
Province and Source Source

Received on: Nov 15 2022 08:30 Reported on: Nov 16 2022 12:48

Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2022-11-17 08:28

Page 1 of 1

Test Flag Result Reference Range - Units

Sample: GIBSONS WATER SYSTEM

SITE 6 SHAW ROAD

Environmental Report

Reported to:

Environmental Water Samplings

Sample Type Drinking water
Method Membrane Filtration
Environmental Health Officer Darren Molder
Site Address Shaw Road
System Type WS1A
Specimen Source Deep Well

Site Treatment No



Reported by: PHSA Environmental

Provincial Health
Services Authority
Province-wide solutions.
Better health.

Collected on: Nov 14 2022 10:27 Received on: Nov 15 2022 08:30 Reported on: Nov 16 2022 12:48

Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2022-11-17 08:28

Page 1 of 1

BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Test Flag Result F

Reference Range - Units

Sample: GIBSONS WATER SYSTEM SITE 8 FRANKLIN ROAD

Environmental Report

Reported to:

Environmental Water Samplings

Sample Type Drinking water
Method Membrane Filtration
Environmental Health Officer Darren Molder
Site Address Franklin Road
System Type WS1A

Specimen Source Deep Well Site Treatment No



Reported by: PHSA Environmental

Collected on: Nov 14 2022 10:36

Received on: Nov 15 2022 08:30

Represented on: Nov 16 2023 13:00

Reported on: Nov 16 2022 13:00
Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2022-11-17 08:28

Page 1 of 1

BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Flag Result

Reference Range - Units

Sample: GIBSONS WATER SYSTEM

Test

SITE 9 BALLS LANE

Environmental Report

Reported to:

Environmental Water Samplings

Sample Type Drinking water
Method Membrane Filtration
Environmental Health Officer Darren Molder
Site Address Balls Lane
System Type WS1A
Specimen Source Deep Well

Site Treatment No

BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)



Reported by: PHSA Environmental

Provincial Health
Services Authority
Province-wide solutions.
Better health.

Collected on: Nov 23 2022 09:44
Received on: Nov 24 2022 08:30
Reported on: Nov 25 2022 10:21

Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2022-11-28 08:56

Page 1 of 1

Test Flag Result Reference Range - Units

Sample: GIBSONS WATER SYSTEM

SITE 10 SCHOOL ROAD RESERVOIR

Environmental Report

Reported to:

Environmental Water Samplings

Sample Type Drinking water
Method Membrane Filtration
Environmental Health Officer Darren Molder
Site Address School Road
System Type WS1A
Specimen Source Deep Well

Site Treatment No



Reported by: PHSA Environmental

Provincial Health
Services Authority
Province-vide solutions.
Better health.

Collected on: Nov 23 2022 08:41 Received on: Nov 24 2022 08:30 Reported on: Nov 25 2022 10:21

Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2022-11-28 08:56

Page 1 of 1

BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Flag Result

Reference Range - Units

Sample: GIBSONS WATER SYSTEM

Test

SITE 13 PARKLAND RESERVOIR SAMPLE PORT LOW

Environmental Report

Reported to:

Environmental Water Samplings

Sample Type Drinking water
Method Membrane Filtration
Environmental Health Officer Darren Molder
Site Address Parkland
System Type WS1A
Specimen Source Deep Well

Site Treatment No



Reported by: PHSA Environmental

Collected on: Nov 23 2022 09:22

Received on: Nov 24 2022 08:30

Reported on: Nov 25 2022 10:13

Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2022-11-28 08:56

Page 1 of 1

BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Flag Result

Reference Range - Units

Sample: GIBSONS WATER SYSTEM

SITE 14 DAVIS ROAD

Test

Environmental Report

Reported to:

Environmental Water Samplings

Sample Type Drinking water
Method Membrane Filtration
Environmental Health Officer Darren Molder
Site Address Davis Road
System Type WS1A
Specimen Source Deep Well

Site Treatment No



Reported by: PHSA Environmental

Provincial Health
Services Authority
Better health

Collected on: Nov 23 2022 10:43
Received on: Nov 24 2022 08:30
Reported on: Nov 25 2022 10:21

Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2022-11-28 08:56

Page 1 of 1

BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Test Flag Result

Reference Range - Units

Sample: GIBSONS WATER SYSTEM SITE 15 ARBUTUS REACH

Environmental Report

Reported to:

Environmental Water Samplings

Sample Type Drinking water
Method Membrane Filtration
Environmental Health Officer Darren Molder
Site Address Arbutus Reach
System Type WS1A

Specimen Source Deep Well
Site Treatment No



Reported by: PHSA Environmental

Provincial Health
Services Authority
Province-wide solutions.
Better health.

Collected on: Nov 23 2022 09:01 Received on: Nov 24 2022 08:30 Reported on: Nov 25 2022 10:21

Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2022-11-28 08:56

Page 1 of 1

BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Test Flag Result F

Reference Range - Units

Sample: GIBSONS WATER SYSTEM

SITE 2 PARK ROAD

Environmental Report

Reported to:

Environmental Water Samplings

Sample Type Drinking water
Method Membrane Filtration
Environmental Health Officer Darren Molder
Site Address Park Road
System Type WS1A
Specimen Source Combined
Site Treatment Yes



Reported by: PHSA Environmental

Provincial Health Services Authority Province-wide solutions.

Collected on: Nov 23 2022 09:11 Received on: Nov 24 2022 08:30 Reported on: Nov 25 2022 10:13

Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2022-11-28 08:56 BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Page 1 of 1

Test Flag Result Reference Range - Units

Sample: GIBSONS WATER SYSTEM

SITE 4 KIWANIS

Environmental Report

Reported to:

Environmental Water Samplings

Sample Type Drinking water Method Membrane Filtration **Environmental Health Officer** Darren Molder Site Address Upper Gibsons

WS1A System Type Specimen Source Combined Site Treatment Yes



Reported by: PHSA Environmental

Provincial Health Services Authority Province-wide solutions.

Collected on: Nov 23 2022 09:34 Received on: Nov 24 2022 08:30 Reported on: Nov 25 2022 10:21

Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2022-11-28 08:56

Page 1 of 1

BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT) Flag Result

Reference Range - Units

Sample: GIBSONS WATER SYSTEM

SITE 5 GIBSONS WAY

Test

Environmental Report

Reported to:

Environmental Water Samplings

Sample Type Drinking water Method Membrane Filtration **Environmental Health Officer** Darren Molder Site Address Highway 101 WS1A System Type Specimen Source Combined Site Treatment Yes



Reported by: PHSA Environmental

Provincial Health Collected on: Nov 23 2022 09:27 Services Authority Received on: Nov 24 2022 08:30 Province-wide solutions. Reported on: Nov 25 2022 10:21

Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2022-11-28 08:56

Page 1 of 1

BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT) Test Flag Result Reference Range - Units

Sample: GIBSONS WATER SYSTEM

SITE 6 SHAW ROAD

Environmental Report

Reported to:

Environmental Water Samplings

Sample Type Drinking water Method Membrane Filtration **Environmental Health Officer** Darren Molder Site Address Shaw Road WS1A System Type Specimen Source Deep Well

Site Treatment No



Reported by: PHSA Environmental

Provincial Health Collected on: Nov 23 2022 10:14 Services Authority Received on: Nov 24 2022 08:30 Province-wide solutions.

Reported on: Nov 25 2022 10:21 Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2022-11-28 08:56

Page 1 of 1

BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT) Flag Result

Reference Range - Units

Sample: GIBSONS WATER SYSTEM

Test

SITE 7 ABBS ROAD

Environmental Report

Reported to:

Environmental Water Samplings

Sample Type Drinking water Method Membrane Filtration **Environmental Health Officer** Darren Molder Site Address Abbs Road WS1A System Type Specimen Source Deep Well

Site Treatment No



Reported by: PHSA Environmental

Provincial Health Services Authority Province-wide solutions.

Collected on: Nov 23 2022 10:48 Received on: Nov 24 2022 08:30 Reported on: Nov 25 2022 10:21

Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2022-11-28 08:56

Page 1 of 1

BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT) Test Flag Result Reference Range - Units

Sample: GIBSONS WATER SYSTEM SITE 8 FRANKLIN ROAD

Environmental Report

Reported to:

Environmental Water Samplings

Sample Type Drinking water Method Membrane Filtration **Environmental Health Officer** Darren Molder Site Address Franklin Road WS1A System Type

Specimen Source Deep Well Site Treatment No



Reported by: PHSA Environmental

Provincial Health Services Authority Province-wide solutions.

Collected on: Nov 23 2022 10:08 Received on: Nov 24 2022 08:30 Reported on: Nov 25 2022 10:21

Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2022-11-28 08:56 BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Page 1 of 1

Test Flag Result Reference Range - Units

Sample: GIBSONS WATER SYSTEM

SITE 9 BALLS LANE

Environmental Report

Reported to:

Environmental Water Samplings

Sample Type Drinking water Method Membrane Filtration **Environmental Health Officer** Darren Molder Site Address Balls Lane WS1A System Type Specimen Source Deep Well

Site Treatment No



Reported by: PHSA Environmental

Reference Range - Units

Collected on: Nov 23 2022 10:31 Received on: Nov 24 2022 08:30 Reported on: Nov 25 2022 10:21

Provincial Health Services Authority Province-wide solutions.

Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2022-11-28 08:56 BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Flag Result

Page 1 of 1

Sample: GIBSONS WATER SYSTEM

Test

WELL 1

Environmental Report

Reported to:

Environmental Water Samplings

Sample Type Drinking water Method Membrane Filtration **Environmental Health Officer** Darren Molder Gower Point Road Site Address

WS1A System Type Specimen Source Deep Well Site Treatment No



Reported by: PHSA Environmental

Collected on: Nov 23 2022 10:23
Received on: Nov 24 2022 08:30
Reported on: Nov 25 2022 10:13

Flag Result

| Services Authority | Province-wide solutions. | Better health.

Provincial Health

Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2022-11-28 08:56

Page 1 of 1

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Reference Range - Units

Sample: GIBSONS WATER SYSTEM

Test

WELL 3

Environmental Report

Environmental Water Samplings

Sample Type Drinking water
Method Membrane Filtration
Environmental Health Officer Darren Molder

Site Address Winn T Gower Point Road

System Type WS1A
Specimen Source Deep Well
Site Treatment No



Reported by: PHSA Environmental

Provincial Health
Services Authority
Province wide solutions.
Better health.

Collected on: Nov 23 2022 10:02 Received on: Nov 24 2022 08:30 Reported on: Nov 25 2022 10:21

Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2022-11-28 08:56

Page 1 of 1

BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Flag Result

Reference Range - Units

Sample: GIBSONS WATER SYSTEM

Test

WELL 4

Environmental Report

Reported to:

Environmental Water Samplings

Sample Type Drinking water
Method Membrane Filtration
Environmental Health Officer Darren Molder
Site Address Gower Point Road

System Type WS1A
Specimen Source Deep Well

Site Treatment No