

Reported by: PHSA Environmental

Collected on: Mar 01 2023 10:03

Received on: Mar 02 2023 08:30

Reported on: Mar 03 2023 09:17



Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2023-03-06 09:28

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Page 1 of 1

Test	Flag Result	Reference Range - Units
------	-------------	-------------------------

Sample: GIBSONS WATER SYSTEM  
SITE 10 SCHOOL ROAD RESERVOIR

**Environmental Report****Environmental Water Samplings**

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	School Road	
System Type	WS1A	
Specimen Source	Deep Well	
Site Treatment	No	
Free Chlorine Level (ppm)	0.40	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental

Collected on: Mar 01 2023 10:38

Received on: Mar 02 2023 08:30

Reported on: Mar 03 2023 09:17



Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2023-03-06 09:28

Page 1 of 1

Test	Flag Result	Reference Range - Units
------	-------------	-------------------------

Sample: GIBSONS WATER SYSTEM  
SITE 13 PARKLAND RESERVOIR SAMPLE PORT LOW

**Environmental Report****Environmental Water Samplings**

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	Parkland	
System Type	WS1A	
Specimen Source	Deep Well	
Site Treatment	No	
Free Chlorine Level (ppm)	0.40	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental

Collected on: Mar 01 2023 09:46

Received on: Mar 02 2023 08:30

Reported on: Mar 03 2023 09:17



Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2023-03-06 09:28

Page 1 of 1

Test	Flag	Result	Reference Range - Units
------	------	--------	-------------------------

Sample: GIBSONS WATER SYSTEM  
SITE 15 ARBUTUS REACH

**Environmental Report****Environmental Water Samplings**

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	Arbutus Reach	
System Type	WS1A	
Specimen Source	Deep Well	
Site Treatment	No	
Free Chlorine Level (ppm)	0.36	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental

Collected on: Mar 01 2023 10:17

Received on: Mar 02 2023 08:30

Reported on: Mar 03 2023 09:17



Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2023-03-06 09:28

Page 1 of 1

Test	Flag	Result	Reference Range - Units
------	------	--------	-------------------------

Sample: GIBSONS WATER SYSTEM  
SITE 5 GIBSONS WAY

**Environmental Report****Environmental Water Samplings**

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	Highway 101	
System Type	WS1A	
Specimen Source	Combined	
Site Treatment	Yes	
Free Chlorine Level (ppm)	0.39	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental

Collected on: Mar 01 2023 09:54

Received on: Mar 02 2023 08:30

Reported on: Mar 03 2023 09:17



Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2023-03-06 09:28

Page 1 of 1

Test	Flag Result	Reference Range - Units
------	-------------	-------------------------

Sample: GIBSONS WATER SYSTEM  
SITE 7 ABBS ROAD

**Environmental Report****Environmental Water Samplings**

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	Abbs Road	
System Type	WS1A	
Specimen Source	Deep Well	
Site Treatment	No	
Free Chlorine Level (ppm)	0.37	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental

Collected on: Mar 01 2023 09:36

Received on: Mar 02 2023 08:30

Reported on: Mar 03 2023 09:17



Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2023-03-06 09:28

Page 1 of 1

Test	Flag	Result	Reference Range - Units
------	------	--------	-------------------------

Sample: GIBSONS WATER SYSTEM  
SITE 8 FRANKLIN ROAD

**Environmental Report****Environmental Water Samplings**

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	Franklin Road	
System Type	WS1A	
Specimen Source	Deep Well	
Site Treatment	No	
Free Chlorine Level (ppm)	0.41	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental

Collected on: Mar 15 2023 09:25

Received on: Mar 16 2023 08:30

Reported on: Mar 17 2023 10:01



Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2023-03-20 08:52

Page 1 of 1

Test	Flag	Result	Reference Range - Units
------	------	--------	-------------------------

Sample: GIBSONS WATER SYSTEM  
SITE 10 SCHOOL ROAD RESERVOIR

**Environmental Report****Environmental Water Samplings**

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	School Road	
System Type	WS1A	
Specimen Source	Deep Well	
Site Treatment	No	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental

Collected on: Mar 15 2023 10:45

Received on: Mar 16 2023 08:30

Reported on: Mar 17 2023 10:18



Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2023-03-20 08:52

Page 1 of 1

Test	Flag Result	Reference Range - Units
------	-------------	-------------------------

Sample: GIBSONS WATER SYSTEM  
SITE 13 PARKLAND RESERVOIR SAMPLE PORT LOW

**Environmental Report****Environmental Water Samplings**

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	Parkland	
System Type	WS1A	
Specimen Source	Deep Well	
Site Treatment	No	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL



Reported by: PHSA Environmental

Collected on: Mar 15 2023 10:10

Received on: Mar 16 2023 08:30

Reported on: Mar 17 2023 10:18



Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2023-03-20 08:52

Page 1 of 1

Test	Flag Result	Reference Range - Units
------	-------------	-------------------------

Sample: GIBSONS WATER SYSTEM  
SITE 14 DAVIS ROAD

**Environmental Report****Environmental Water Samplings**

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	Davis Road	
System Type	WS1A	
Specimen Source	Deep Well	
Site Treatment	No	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental

Collected on: Mar 15 2023 08:40

Received on: Mar 16 2023 08:30

Reported on: Mar 17 2023 10:18



Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2023-03-20 08:52

Page 1 of 1

Test	Flag	Result	Reference Range - Units
------	------	--------	-------------------------

Sample: GIBSONS WATER SYSTEM  
SITE 15 ARBUTUS REACH

**Environmental Report****Environmental Water Samplings**

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	Arbutus Reach	
System Type	WS1A	
Specimen Source	Deep Well	
Site Treatment	No	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental

Collected on: Mar 15 2023 10:20

Received on: Mar 16 2023 08:30

Reported on: Mar 17 2023 10:01



Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2023-03-20 08:52

Page 1 of 1

Test	Flag	Result	Reference Range - Units
------	------	--------	-------------------------

Sample: GIBSONS WATER SYSTEM  
SITE 2 PARK ROAD

**Environmental Report****Environmental Water Samplings**

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	Park Road	
System Type	WS1A	
Specimen Source	Combined	
Site Treatment	Yes	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental

Collected on: Mar 15 2023 09:48

Received on: Mar 16 2023 08:30

Reported on: Mar 17 2023 10:01



Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2023-03-20 08:52

Page 1 of 1

Test	Flag Result	Reference Range - Units
------	-------------	-------------------------

Sample: GIBSONS WATER SYSTEM  
SITE 4 KIWANIS

**Environmental Report****Environmental Water Samplings**

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	Upper Gibsons	
System Type	WS1A	
Specimen Source	Combined	
Site Treatment	Yes	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental

Collected on: Mar 15 2023 09:38

Received on: Mar 16 2023 08:30

Reported on: Mar 17 2023 10:18



Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2023-03-20 08:52

Page 1 of 1

Test	Flag	Result	Reference Range - Units
------	------	--------	-------------------------

Sample: GIBSONS WATER SYSTEM  
SITE 5 GIBSONS WAY

**Environmental Report****Environmental Water Samplings**

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	Highway 101	
System Type	WS1A	
Specimen Source	Combined	
Site Treatment	Yes	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental

Collected on: Mar 15 2023 10:00

Received on: Mar 16 2023 08:30

Reported on: Mar 17 2023 10:18



Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2023-03-20 08:52

Page 1 of 1

Test	Flag	Result	Reference Range - Units
------	------	--------	-------------------------

Sample: GIBSONS WATER SYSTEM  
SITE 6 SHAW ROAD

**Environmental Report****Environmental Water Samplings**

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	Shaw Road	
System Type	WS1A	
Specimen Source	Deep Well	
Site Treatment	No	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental

Collected on: Mar 15 2023 08:55

Received on: Mar 16 2023 08:30

Reported on: Mar 17 2023 10:01



Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2023-03-20 08:52

Page 1 of 1

Test	Flag	Result	Reference Range - Units
------	------	--------	-------------------------

Sample: GIBSONS WATER SYSTEM  
SITE 7 ABBS ROAD

**Environmental Report****Environmental Water Samplings**

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	Abbs Road	
System Type	WS1A	
Specimen Source	Deep Well	
Site Treatment	No	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental

Collected on: Mar 15 2023 08:26

Received on: Mar 16 2023 08:30

Reported on: Mar 17 2023 10:01



Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2023-03-20 08:52

Page 1 of 1

Test	Flag Result	Reference Range - Units
------	-------------	-------------------------

Sample: GIBSONS WATER SYSTEM  
SITE 8 FRANKLIN ROAD

**Environmental Report****Environmental Water Samplings**

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	Franklin Road	
System Type	WS1A	
Specimen Source	Deep Well	
Site Treatment	No	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL



Reported by: PHSA Environmental

Collected on: Mar 15 2023 09:10

Received on: Mar 16 2023 08:30

Reported on: Mar 17 2023 10:01



Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2023-03-20 08:52

Page 1 of 1

Test	Flag	Result	Reference Range - Units
------	------	--------	-------------------------

Sample: GIBSONS WATER SYSTEM  
SITE 9 BALLS LANE

**Environmental Report****Environmental Water Samplings**

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	Balls Lane	
System Type	WS1A	
Specimen Source	Deep Well	
Site Treatment	No	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental

Collected on: Mar 21 2023 08:35

Received on: Mar 22 2023 08:30

Reported on: Mar 23 2023 11:27



Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2023-03-24 08:40

Page 1 of 1

Test	Flag	Result	Reference Range - Units
------	------	--------	-------------------------

Sample: GIBSONS WATER SYSTEM  
SITE 10 SCHOOL ROAD RESERVOIR

**Environmental Report****Environmental Water Samplings**

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	School Road	
System Type	WS1A	
Specimen Source	Deep Well	
Site Treatment	No	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental

Collected on: Mar 21 2023 09:20

Received on: Mar 22 2023 11:40

Reported on: Mar 23 2023 11:33



Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2023-03-24 08:40

Page 1 of 1

Test	Flag	Result	Reference Range - Units
------	------	--------	-------------------------

Sample: GIBSONS WATER SYSTEM  
SITE 13 PARKLAND RESERVOIR SAMPLE PORT LOW

**Environmental Report****Environmental Water Samplings**

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	Parkland	
System Type	WS1A	
Specimen Source	Deep Well	
Site Treatment	No	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental

Collected on: Mar 21 2023 08:55

Received on: Mar 22 2023 11:45

Reported on: Mar 23 2023 11:33



Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2023-03-24 08:40

Page 1 of 1

Test	Flag	Result	Reference Range - Units
------	------	--------	-------------------------

Sample: GIBSONS WATER SYSTEM  
SITE 6 SHAW ROAD

**Environmental Report****Environmental Water Samplings**

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	Shaw Road	
System Type	WS1A	
Specimen Source	Deep Well	
Site Treatment	No	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental

Collected on: Mar 21 2023 09:00

Received on: Mar 22 2023 11:41

Reported on: Mar 23 2023 11:33



Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2023-03-24 08:40

Page 1 of 1

Test	Flag	Result	Reference Range - Units
------	------	--------	-------------------------

Sample: GIBSONS WATER SYSTEM  
SITE 8 FRANKLIN ROAD

**Environmental Report****Environmental Water Samplings**

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	Franklin Road	
System Type	WS1A	
Specimen Source	Deep Well	
Site Treatment	No	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental

Collected on: Mar 21 2023 08:20

Received on: Mar 22 2023 11:53

Reported on: Mar 23 2023 11:33



Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Reported to: BCCDC LAB COPY, REGIONAL DISTRICT SUNSHINE COAST,  
VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2023-03-24 08:40

Page 1 of 1

Test	Flag Result	Reference Range - Units
------	-------------	-------------------------

Sample: GIBSONS WATER SYSTEM  
SITE 9 BALLS LANE**Environmental Report****Environmental Water Samplings**

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	Balls Lane	
System Type	WS1A	
Specimen Source	Deep Well	
Site Treatment	No	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental

Collected on: Mar 28 2023 10:38

Received on: Mar 29 2023 08:30

Reported on: Mar 30 2023 11:11



Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2023-03-31 08:24

Page 1 of 1

Test	Flag	Result	Reference Range - Units
------	------	--------	-------------------------

Sample: GIBSONS WATER SYSTEM  
SITE 10 SCHOOL ROAD RESERVOIR

**Environmental Report****Environmental Water Samplings**

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	School Road	
System Type	WS1A	
Specimen Source	Deep Well	
Site Treatment	No	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental

Collected on: Mar 28 2023 09:45

Received on: Mar 29 2023 08:30

Reported on: Mar 30 2023 11:11



Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2023-03-31 08:24

Page 1 of 1

Test	Flag	Result	Reference Range - Units
------	------	--------	-------------------------

Sample: GIBSONS WATER SYSTEM  
SITE 13 PARKLAND RESERVOIR SAMPLE PORT LOW

**Environmental Report****Environmental Water Samplings**

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	Parkland	
System Type	WS1A	
Specimen Source	Deep Well	
Site Treatment	No	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL



Reported by: PHSA Environmental

Collected on: Mar 28 2023 10:15

Received on: Mar 29 2023 08:30

Reported on: Mar 30 2023 13:20



Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2023-03-31 08:24

Page 1 of 1

Test	Flag	Result	Reference Range - Units
------	------	--------	-------------------------

Sample: GIBSONS WATER SYSTEM  
SITE 14 DAVIS ROAD

**Environmental Report****Environmental Water Samplings**

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	Davis Road	
System Type	WS1A	
Specimen Source	Deep Well	
Boil Advisory	No	
Site Treatment	No	
Free Chlorine Level (ppm)	0.50	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental

Collected on: Mar 28 2023 11:25

Received on: Mar 29 2023 08:30

Reported on: Mar 30 2023 11:11



Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2023-03-31 08:24

Page 1 of 1

Test	Flag	Result	Reference Range - Units
------	------	--------	-------------------------

Sample: GIBSONS WATER SYSTEM  
SITE 15 ARBUTUS REACH

**Environmental Report****Environmental Water Samplings**

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	Arbutus Reach	
System Type	WS1A	
Specimen Source	Deep Well	
Site Treatment	No	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental

Collected on: Mar 28 2023 10:24

Received on: Mar 29 2023 08:30

Reported on: Mar 30 2023 13:20



Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2023-03-31 08:24

Page 1 of 1

Test	Flag	Result	Reference Range - Units
------	------	--------	-------------------------

Sample: GIBSONS WATER SYSTEM  
SITE 2 PARK ROAD

**Environmental Report****Environmental Water Samplings**

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	Park Road	
System Type	WS1A	
Specimen Source	Combined	
Boil Advisory	No	
Site Treatment	Yes	
Free Chlorine Level (ppm)	0.47	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental

Collected on: Mar 28 2023 09:53

Received on: Mar 29 2023 08:30

Reported on: Mar 30 2023 13:20



Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2023-03-31 08:24

Page 1 of 1

Test	Flag	Result	Reference Range - Units
------	------	--------	-------------------------

Sample: GIBSONS WATER SYSTEM  
SITE 4 KIWANIS

**Environmental Report****Environmental Water Samplings**

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	Upper Gibsons	
System Type	WS1A	
Specimen Source	Combined	
Boil Advisory	No	
Site Treatment	Yes	
Free Chlorine Level (ppm)	0.48	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental

Collected on: Mar 28 2023 10:02

Received on: Mar 29 2023 08:30

Reported on: Mar 30 2023 11:11



Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2023-03-31 08:24

Page 1 of 1

Test	Flag	Result	Reference Range - Units
------	------	--------	-------------------------

Sample: GIBSONS WATER SYSTEM  
SITE 5 GIBSONS WAY

**Environmental Report****Environmental Water Samplings**

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	Highway 101	
System Type	WS1A	
Specimen Source	Combined	
Site Treatment	Yes	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental

Collected on: Mar 28 2023 10:11

Received on: Mar 29 2023 08:30

Reported on: Mar 30 2023 11:11



Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2023-03-31 08:24

Page 1 of 1

Test	Flag	Result	Reference Range - Units
------	------	--------	-------------------------

Sample: GIBSONS WATER SYSTEM  
SITE 6 SHAW ROAD

**Environmental Report****Environmental Water Samplings**

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	Shaw Road	
System Type	WS1A	
Specimen Source	Deep Well	
Site Treatment	No	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental

Collected on: Mar 28 2023 11:37

Received on: Mar 29 2023 08:30

Reported on: Mar 30 2023 11:11



Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2023-03-31 08:24

Page 1 of 1

Test	Flag	Result	Reference Range - Units
------	------	--------	-------------------------

Sample: GIBSONS WATER SYSTEM  
SITE 7 ABBS ROAD

**Environmental Report****Environmental Water Samplings**

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	Abbs Road	
System Type	WS1A	
Specimen Source	Deep Well	
Site Treatment	No	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental

Collected on: Mar 28 2023 11:32

Received on: Mar 29 2023 08:30

Reported on: Mar 30 2023 11:11



Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2023-03-31 08:24

Page 1 of 1

Test	Flag	Result	Reference Range - Units
------	------	--------	-------------------------

Sample: GIBSONS WATER SYSTEM  
SITE 8 FRANKLIN ROAD

**Environmental Report****Environmental Water Samplings**

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	Franklin Road	
System Type	WS1A	
Specimen Source	Deep Well	
Site Treatment	No	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL



Reported by: PHSA Environmental

Collected on: Mar 28 2023 10:55

Received on: Mar 29 2023 08:30

Reported on: Mar 30 2023 11:11



Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2023-03-31 08:24

Page 1 of 1

Test	Flag	Result	Reference Range - Units
------	------	--------	-------------------------

Sample: GIBSONS WATER SYSTEM  
SITE 9 BALLS LANE

**Environmental Report****Environmental Water Samplings**

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	Balls Lane	
System Type	WS1A	
Specimen Source	Deep Well	
Site Treatment	No	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental

Collected on: Mar 28 2023 11:11

Received on: Mar 29 2023 08:30

Reported on: Mar 30 2023 11:11



Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2023-03-31 08:24

Page 1 of 1

Test	Flag	Result	Reference Range - Units
------	------	--------	-------------------------

Sample: GIBSONS WATER SYSTEM  
WELL 1

**Environmental Report****Environmental Water Samplings**

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	Gower Point Road	
System Type	WS1A	
Specimen Source	Deep Well	
Site Treatment	No	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental

Collected on: Mar 28 2023 11:16

Received on: Mar 29 2023 08:30

Reported on: Mar 30 2023 11:11



Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2023-03-31 08:24

Page 1 of 1

Test	Flag	Result	Reference Range - Units
------	------	--------	-------------------------

Sample: GIBSONS WATER SYSTEM  
WELL 3

**Environmental Report****Environmental Water Samplings**

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	Winn T Gower Point Road	
System Type	WS1A	
Specimen Source	Deep Well	
Site Treatment	No	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental

Collected on: Mar 28 2023 11:02

Received on: Mar 29 2023 08:30

Reported on: Mar 30 2023 11:11



Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2023-03-31 08:24

Page 1 of 1

Test	Flag	Result	Reference Range - Units
------	------	--------	-------------------------

Sample: GIBSONS WATER SYSTEM  
WELL 4

**Environmental Report****Environmental Water Samplings**

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	Gower Point Road	
System Type	WS1A	
Specimen Source	Deep Well	
Site Treatment	No	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL