

Reported by: PHSA Environmental



Collected on: Apr 05 2023 07:46

Received on: Apr 06 2023 08:30

Reported on: Apr 07 2023 10:25

Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2023-04-12 08:03

Page 1 of 1

Test	Flag	Result	Reference Range - Units
------	------	--------	-------------------------

Sample: GIBSONS WATER SYSTEM
SITE 10 SCHOOL ROAD RESERVOIR

Environmental Report**Environmental Water Samplings**

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	School Road	
System Type	WS1A	
Specimen Source	Deep Well	
Site Treatment	No	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental

Collected on: Apr 05 2023 08:06

Received on: Apr 06 2023 08:30

Reported on: Apr 07 2023 10:25



Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2023-04-12 08:03

Page 1 of 1

Test	Flag	Result	Reference Range - Units
------	------	--------	-------------------------

Sample: GIBSONS WATER SYSTEM
SITE 13 PARKLAND RESERVOIR SAMPLE PORT LOW

Environmental Report**Environmental Water Samplings**

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	Parkland	
System Type	WS1A	
Specimen Source	Deep Well	
Site Treatment	No	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental



Collected on: Apr 05 2023 07:54

Received on: Apr 06 2023 08:30

Reported on: Apr 07 2023 10:25

Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2023-04-12 08:03

Page 1 of 1

Test	Flag	Result	Reference Range - Units
------	------	--------	-------------------------

Sample: GIBSONS WATER SYSTEM
SITE 6 SHAW ROAD

Environmental Report**Environmental Water Samplings**

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	Shaw Road	
System Type	WS1A	
Specimen Source	Deep Well	
Site Treatment	No	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental

Collected on: Apr 05 2023 07:21

Received on: Apr 06 2023 08:30

Reported on: Apr 07 2023 10:25



Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2023-04-12 08:03

Page 1 of 1

Test	Flag	Result	Reference Range - Units
------	------	--------	-------------------------

Sample: GIBSONS WATER SYSTEM
SITE 8 FRANKLIN ROAD

Environmental Report**Environmental Water Samplings**

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	Franklin Road	
System Type	WS1A	
Specimen Source	Deep Well	
Site Treatment	No	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental

Collected on: Apr 05 2023 07:38

Received on: Apr 06 2023 08:30

Reported on: Apr 07 2023 10:25



Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2023-04-12 08:03

Page 1 of 1

Test	Flag	Result	Reference Range - Units
------	------	--------	-------------------------

Sample: GIBSONS WATER SYSTEM
SITE 9 BALLS LANE

Environmental Report**Environmental Water Samplings**

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	Balls Lane	
System Type	WS1A	
Specimen Source	Deep Well	
Site Treatment	No	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental

Collected on: Apr 12 2023 09:24

Received on: Apr 13 2023 08:30

Reported on: Apr 14 2023 09:58



Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2023-04-14 10:59

Page 1 of 1

Test	Flag	Result	Reference Range - Units
------	------	--------	-------------------------

Sample: GIBSONS WATER SYSTEM
SITE 10 SCHOOL ROAD RESERVOIR

Environmental Report**Environmental Water Samplings**

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	School Road	
System Type	WS1A	
Specimen Source	Deep Well	
Site Treatment	No	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental



Collected on: Apr 12 2023 08:29

Received on: Apr 13 2023 08:30

Reported on: Apr 14 2023 09:57

Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2023-04-14 10:59

Page 1 of 1

Test	Flag	Result	Reference Range - Units
------	------	--------	-------------------------

Sample: GIBSONS WATER SYSTEM
SITE 13 PARKLAND RESERVOIR SAMPLE PORT LOW

Environmental Report**Environmental Water Samplings**

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	Parkland	
System Type	WS1A	
Specimen Source	Deep Well	
Site Treatment	No	
Total Coliform	1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental

Collected on: Apr 12 2023 09:11

Received on: Apr 13 2023 08:30

Reported on: Apr 14 2023 09:58



Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2023-04-14 10:59

Page 1 of 1

Test	Flag	Result	Reference Range - Units
------	------	--------	-------------------------

Sample: GIBSONS WATER SYSTEM
SITE 14 DAVIS ROAD

Environmental Report**Environmental Water Samplings**

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	Davis Road	
System Type	WS1A	
Specimen Source	Deep Well	
Site Treatment	No	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental

Collected on: Apr 12 2023 09:51

Received on: Apr 13 2023 08:30

Reported on: Apr 14 2023 09:58



Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2023-04-14 10:59

Page 1 of 1

Test	Flag	Result	Reference Range - Units
------	------	--------	-------------------------

Sample: GIBSONS WATER SYSTEM
SITE 15 ARBUTUS REACH

Environmental Report**Environmental Water Samplings**

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	Arbutus Reach	
System Type	WS1A	
Specimen Source	Deep Well	
Site Treatment	No	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental

Collected on: Apr 12 2023 08:41

Received on: Apr 13 2023 08:30

Reported on: Apr 14 2023 09:58



Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2023-04-14 10:59

Page 1 of 1

Test	Flag	Result	Reference Range - Units
------	------	--------	-------------------------

Sample: GIBSONS WATER SYSTEM
SITE 2 PARK ROAD

Environmental Report**Environmental Water Samplings**

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	Park Road	
System Type	WS1A	
Specimen Source	Combined	
Site Treatment	Yes	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental

Collected on: Apr 12 2023 08:58

Received on: Apr 13 2023 08:30

Reported on: Apr 14 2023 09:58



Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2023-04-14 10:59

Page 1 of 1

Test	Flag	Result	Reference Range - Units
------	------	--------	-------------------------

Sample: GIBSONS WATER SYSTEM
SITE 5 GIBSONS WAY

Environmental Report**Environmental Water Samplings**

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	Highway 101	
System Type	WS1A	
Specimen Source	Combined	
Site Treatment	Yes	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental

Collected on: Apr 12 2023 09:06

Received on: Apr 13 2023 08:30

Reported on: Apr 14 2023 09:58



Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2023-04-14 10:59

Page 1 of 1

Test	Flag	Result	Reference Range - Units
------	------	--------	-------------------------

Sample: GIBSONS WATER SYSTEM
SITE 6 SHAW ROAD

Environmental Report**Environmental Water Samplings**

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	Shaw Road	
System Type	WS1A	
Specimen Source	Deep Well	
Site Treatment	No	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental



Collected on: Apr 12 2023 09:30

Received on: Apr 13 2023 08:30

Reported on: Apr 14 2023 09:58

Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2023-04-14 10:59

Page 1 of 1

Test	Flag	Result	Reference Range - Units
------	------	--------	-------------------------

Sample: GIBSONS WATER SYSTEM
SITE 7 ABBS ROAD

Environmental Report**Environmental Water Samplings**

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	Abbs Road	
System Type	WS1A	
Specimen Source	Deep Well	
Site Treatment	No	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental

Collected on: Apr 12 2023 09:57

Received on: Apr 13 2023 08:30

Reported on: Apr 14 2023 09:58



Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2023-04-14 10:59

Page 1 of 1

Test	Flag	Result	Reference Range - Units
------	------	--------	-------------------------

Sample: GIBSONS WATER SYSTEM
SITE 8 FRANKLIN ROAD

Environmental Report**Environmental Water Samplings**

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	Franklin Road	
System Type	WS1A	
Specimen Source	Deep Well	
Site Treatment	No	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental

Collected on: Apr 12 2023 10:11

Received on: Apr 13 2023 08:30

Reported on: Apr 14 2023 09:58



Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2023-04-14 10:59

Page 1 of 1

Test	Flag	Result	Reference Range - Units
------	------	--------	-------------------------

Sample: GIBSONS WATER SYSTEM
SITE 9 BALLS LANE

Environmental Report**Environmental Water Samplings**

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	Balls Lane	
System Type	WS1A	
Specimen Source	Deep Well	
Site Treatment	No	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental

Collected on: Apr 12 2023 08:52

Received on: Apr 13 2023 08:30

Reported on: Apr 14 2023 11:15



Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2023-04-17 09:04

Page 1 of 1

Test	Flag	Result	Reference Range - Units
------	------	--------	-------------------------

Sample: GIBSONS WATER SYSTEM
SITE 4 KIWANIS

Environmental Report**Environmental Water Samplings**

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	Upper Gibsons	
System Type	WS1A	
Specimen Source	Combined	
Site Treatment	Yes	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental



Collected on: Apr 17 2023 08:44

Received on: Apr 18 2023 08:30

Reported on: Apr 19 2023 11:58

Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2023-04-20 09:01

Page 1 of 1

Test	Flag	Result	Reference Range - Units
------	------	--------	-------------------------

Sample: GIBSONS WATER SYSTEM
SITE 10 SCHOOL ROAD RESERVOIR

Environmental Report

Environmental Water Samplings

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	School Road	
System Type	WS1A	
Specimen Source	Deep Well	
Site Treatment	No	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental

Collected on: Apr 17 2023 09:26

Received on: Apr 18 2023 08:30

Reported on: Apr 19 2023 11:58



Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2023-04-20 09:01

Page 1 of 1

Test	Flag Result	Reference Range - Units
------	-------------	-------------------------

Sample: GIBSONS WATER SYSTEM
SITE 13 PARKLAND RESERVOIR SAMPLE PORT LOW

Environmental Report**Environmental Water Samplings**

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	Parkland	
System Type	WS1A	
Specimen Source	Deep Well	
Site Treatment	No	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental

Collected on: Apr 17 2023 08:58

Received on: Apr 18 2023 08:30

Reported on: Apr 19 2023 11:19



Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2023-04-20 09:01

Page 1 of 1

Test	Flag	Result	Reference Range - Units
------	------	--------	-------------------------

Sample: GIBSONS WATER SYSTEM
SITE 6 SHAW ROAD

Environmental Report**Environmental Water Samplings**

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	Shaw Road	
System Type	WS1A	
Specimen Source	Deep Well	
Site Treatment	No	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental

Collected on: Apr 17 2023 08:21

Received on: Apr 18 2023 08:30

Reported on: Apr 19 2023 11:19



Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2023-04-20 09:01

Page 1 of 1

Test	Flag	Result	Reference Range - Units
------	------	--------	-------------------------

Sample: GIBSONS WATER SYSTEM
SITE 8 FRANKLIN ROAD

Environmental Report**Environmental Water Samplings**

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	Franklin Road	
System Type	WS1A	
Specimen Source	Deep Well	
Site Treatment	No	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental

Collected on: Apr 17 2023 08:36

Received on: Apr 18 2023 08:30

Reported on: Apr 19 2023 11:58



Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2023-04-20 09:01

Page 1 of 1

Test	Flag	Result	Reference Range - Units
------	------	--------	-------------------------

Sample: GIBSONS WATER SYSTEM
SITE 9 BALLS LANE

Environmental Report**Environmental Water Samplings**

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	Balls Lane	
System Type	WS1A	
Specimen Source	Deep Well	
Site Treatment	No	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental

Collected on: Apr 27 2023 09:22

Received on: Apr 28 2023 08:30

Reported on: Apr 29 2023 10:20



Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2023-05-01 08:48

Page 1 of 1

Test	Flag	Result	Reference Range - Units
------	------	--------	-------------------------

Sample: GIBSONS WATER SYSTEM
SITE 10 SCHOOL ROAD RESERVOIR

Environmental Report**Environmental Water Samplings**

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	School Road	
System Type	WS1A	
Specimen Source	Deep Well	
Site Treatment	No	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental

Collected on: Apr 27 2023 08:14

Received on: Apr 28 2023 08:30

Reported on: Apr 29 2023 10:20



Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2023-05-01 08:48

Page 1 of 1

Test	Flag	Result	Reference Range - Units
------	------	--------	-------------------------

Sample: GIBSONS WATER SYSTEM
SITE 13 PARKLAND RESERVOIR SAMPLE PORT LOW

Environmental Report**Environmental Water Samplings**

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	Parkland	
System Type	WS1A	
Specimen Source	Deep Well	
Site Treatment	No	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental

Collected on: Apr 27 2023 08:44

Received on: Apr 28 2023 08:30

Reported on: Apr 29 2023 10:20



Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2023-05-01 08:48

Page 1 of 1

Test	Flag	Result	Reference Range - Units
------	------	--------	-------------------------

Sample: GIBSONS WATER SYSTEM
SITE 14 DAVIS ROAD

Environmental Report**Environmental Water Samplings**

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	Davis Road	
System Type	WS1A	
Specimen Source	Deep Well	
Site Treatment	No	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental

Collected on: Apr 27 2023 09:59

Received on: Apr 28 2023 08:30

Reported on: Apr 29 2023 10:20



Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2023-05-01 08:48

Page 1 of 1

Test	Flag	Result	Reference Range - Units
------	------	--------	-------------------------

Sample: GIBSONS WATER SYSTEM
SITE 15 ARBUTUS REACH

Environmental Report**Environmental Water Samplings**

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	Arbutus Reach	
System Type	WS1A	
Specimen Source	Deep Well	
Site Treatment	No	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental

Collected on: Apr 27 2023 08:23

Received on: Apr 28 2023 08:30

Reported on: Apr 29 2023 10:20



Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2023-05-01 08:48

Page 1 of 1

Test	Flag	Result	Reference Range - Units
------	------	--------	-------------------------

Sample: GIBSONS WATER SYSTEM
SITE 2 PARK ROAD

Environmental Report**Environmental Water Samplings**

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	Park Road	
System Type	WS1A	
Specimen Source	Combined	
Site Treatment	Yes	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental

Collected on: Apr 27 2023 08:32

Received on: Apr 28 2023 08:30

Reported on: Apr 29 2023 10:20



Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2023-05-01 08:48

Page 1 of 1

Test	Flag	Result	Reference Range - Units
------	------	--------	-------------------------

Sample: GIBSONS WATER SYSTEM
SITE 4 KIWANIS

Environmental Report**Environmental Water Samplings**

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	Upper Gibsons	
System Type	WS1A	
Specimen Source	Combined	
Site Treatment	Yes	
Laboratory Comment	Requisition was received separately from sample.	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental

Collected on: Apr 27 2023 09:09

Received on: Apr 28 2023 08:30

Reported on: Apr 29 2023 10:20



Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2023-05-01 08:48

Page 1 of 1

Test	Flag	Result	Reference Range - Units
------	------	--------	-------------------------

Sample: GIBSONS WATER SYSTEM
SITE 5 GIBSONS WAY

Environmental Report**Environmental Water Samplings**

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	Highway 101	
System Type	WS1A	
Specimen Source	Combined	
Site Treatment	Yes	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental

Collected on: Apr 27 2023 08:51

Received on: Apr 28 2023 08:30

Reported on: Apr 29 2023 10:20



Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2023-05-01 08:48

Page 1 of 1

Test	Flag	Result	Reference Range - Units
------	------	--------	-------------------------

Sample: GIBSONS WATER SYSTEM
SITE 6 SHAW ROAD

Environmental Report**Environmental Water Samplings**

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	Shaw Road	
System Type	WS1A	
Specimen Source	Deep Well	
Site Treatment	No	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental

Collected on: Apr 27 2023 10:11

Received on: Apr 28 2023 08:30

Reported on: Apr 29 2023 10:20



Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2023-05-01 08:48

Page 1 of 1

Test	Flag	Result	Reference Range - Units
------	------	--------	-------------------------

Sample: GIBSONS WATER SYSTEM
SITE 7 ABBS ROAD

Environmental Report**Environmental Water Samplings**

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	Abbs Road	
System Type	WS1A	
Specimen Source	Deep Well	
Site Treatment	No	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental

Collected on: Apr 27 2023 10:04

Received on: Apr 28 2023 08:30

Reported on: Apr 29 2023 10:20



Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2023-05-01 08:48

Page 1 of 1

Test	Flag	Result	Reference Range - Units
------	------	--------	-------------------------

Sample: GIBSONS WATER SYSTEM
SITE 8 FRANKLIN ROAD

Environmental Report**Environmental Water Samplings**

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	Franklin Road	
System Type	WS1A	
Specimen Source	Deep Well	
Site Treatment	No	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental

Collected on: Apr 27 2023 09:14

Received on: Apr 28 2023 08:30

Reported on: Apr 29 2023 10:20



Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2023-05-01 08:48

Page 1 of 1

Test	Flag	Result	Reference Range - Units
------	------	--------	-------------------------

Sample: GIBSONS WATER SYSTEM
SITE 9 BALLS LANE

Environmental Report**Environmental Water Samplings**

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	Balls Lane	
System Type	WS1A	
Specimen Source	Deep Well	
Site Treatment	No	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental

Collected on: Apr 27 2023 09:32

Received on: Apr 28 2023 08:30

Reported on: Apr 29 2023 10:20



Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2023-05-01 08:48

Page 1 of 1

Test	Flag	Result	Reference Range - Units
------	------	--------	-------------------------

Sample: GIBSONS WATER SYSTEM
WELL 1

Environmental Report**Environmental Water Samplings**

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	Gower Point Road	
System Type	WS1A	
Specimen Source	Deep Well	
Site Treatment	No	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental

Collected on: Apr 27 2023 09:48

Received on: Apr 28 2023 08:30

Reported on: Apr 29 2023 10:20



Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2023-05-01 08:48

Page 1 of 1

Test	Flag	Result	Reference Range - Units
------	------	--------	-------------------------

Sample: GIBSONS WATER SYSTEM
WELL 3

Environmental Report**Environmental Water Samplings**

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	Winn T Gower Point Road	
System Type	WS1A	
Specimen Source	Deep Well	
Site Treatment	No	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental

Collected on: Apr 27 2023 09:28

Received on: Apr 28 2023 08:30

Reported on: Apr 29 2023 10:20



Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2023-05-01 08:48

Page 1 of 1

Test	Flag	Result	Reference Range - Units
------	------	--------	-------------------------

Sample: GIBSONS WATER SYSTEM
WELL 4

Environmental Report**Environmental Water Samplings**

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	Gower Point Road	
System Type	WS1A	
Specimen Source	Deep Well	
Site Treatment	No	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL