

Reported by: PHSA Environmental



Collected on: Jul 05 2023 09:56

Received on: Jul 06 2023 08:30

Reported on: Jul 07 2023 11:13

Ordered by: VANCOUVER COASTAL HEALTH (SECHLT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHLT)

Printed on: 2023-07-10 14:02

Page 1 of 1

Test	Flag	Result	Reference Range - Units
------	------	--------	-------------------------

Sample: GIBSONS WATER SYSTEM
SITE 9 BALLS LANE

Environmental Report**Environmental Water Samplings**

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	Balls Lane	
System Type	WS1A	
Specimen Source	Deep Well	
Site Treatment	No	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental



Collected on: Jul 05 2023 09:43

Received on: Jul 06 2023 08:30

Reported on: Jul 07 2023 11:13

Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2023-07-10 14:02

Page 1 of 1

Test	Flag	Result	Reference Range - Units
------	------	--------	-------------------------

Sample: GIBSONS WATER SYSTEM
SITE 6 SHAW ROAD

Environmental Report**Environmental Water Samplings**

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	Shaw Road	
System Type	WS1A	
Specimen Source	Deep Well	
Site Treatment	No	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental



Collected on: Jul 05 2023 09:27

Received on: Jul 06 2023 08:30

Reported on: Jul 07 2023 11:13

Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2023-07-10 14:02

Page 1 of 1

Test	Flag	Result	Reference Range - Units
------	------	--------	-------------------------

Sample: GIBSONS WATER SYSTEM
SITE 13 PARKLAND RESERVOIR SAMPLE PORT LOW

Environmental Report**Environmental Water Samplings**

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	Parkland	
System Type	WS1A	
Specimen Source	Deep Well	
Site Treatment	No	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental



Collected on: Jul 05 2023 09:17

Received on: Jul 06 2023 08:30

Reported on: Jul 07 2023 11:13

Ordered by: VANCOUVER COASTAL HEALTH (SECHLT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHLT)

Printed on: 2023-07-10 14:02

Page 1 of 1

Test	Flag	Result	Reference Range - Units
------	------	--------	-------------------------

Sample: GIBSONS WATER SYSTEM
SITE 10 SCHOOL ROAD RESERVOIR

Environmental Report**Environmental Water Samplings**

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	School Road	
System Type	WS1A	
Specimen Source	Deep Well	
Site Treatment	No	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental



Collected on: Jul 11 2023 09:39

Received on: Jul 12 2023 08:30

Reported on: Jul 13 2023 12:12

Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2023-07-14 10:43

Page 1 of 1

Test	Flag	Result	Reference Range - Units
------	------	--------	-------------------------

Sample: GIBSONS WATER SYSTEM
SITE 7 ABBS ROAD

Environmental Report**Environmental Water Samplings**

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	Abbs Road	
System Type	WS1A	
Specimen Source	Deep Well	
Site Treatment	No	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental



Collected on: Jul 11 2023 09:47

Received on: Jul 12 2023 08:30

Reported on: Jul 13 2023 12:12

Ordered by: VANCOUVER COASTAL HEALTH (SECHLT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHLT)

Printed on: 2023-07-14 10:43

Page 1 of 1

Test	Flag	Result	Reference Range - Units
------	------	--------	-------------------------

Sample: GIBSONS WATER SYSTEM
SITE 8 FRANKLIN ROAD

Environmental Report**Environmental Water Samplings**

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	Franklin Road	
System Type	WS1A	
Specimen Source	Deep Well	
Site Treatment	No	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental



Collected on: Jul 11 2023 10:09

Received on: Jul 12 2023 08:30

Reported on: Jul 13 2023 12:12

Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2023-07-14 10:43

Page 1 of 1

Test	Flag	Result	Reference Range - Units
------	------	--------	-------------------------

Sample: GIBSONS WATER SYSTEM
SITE 9 BALLS LANE

Environmental Report**Environmental Water Samplings**

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	Balls Lane	
System Type	WS1A	
Specimen Source	Deep Well	
Site Treatment	No	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental



Collected on: Jul 11 2023 08:54

Received on: Jul 12 2023 08:30

Reported on: Jul 13 2023 12:12

Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2023-07-14 10:43

Page 1 of 1

Test	Flag	Result	Reference Range - Units
------	------	--------	-------------------------

Sample: GIBSONS WATER SYSTEM
SITE 10 SCHOOL ROAD RESERVOIR

Environmental Report**Environmental Water Samplings**

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	School Road	
System Type	WS1A	
Specimen Source	Deep Well	
Site Treatment	No	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental



Collected on: Jul 11 2023 08:43

Received on: Jul 12 2023 08:30

Reported on: Jul 13 2023 12:12

Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2023-07-14 10:43

Page 1 of 1

Test	Flag	Result	Reference Range - Units
------	------	--------	-------------------------

Sample: GIBSONS WATER SYSTEM
SITE 4 KIWANIS

Environmental Report**Environmental Water Samplings**

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	Upper Gibsons	
System Type	WS1A	
Specimen Source	Combined	
Site Treatment	Yes	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental



Collected on: Jul 10 2023 11:23

Received on: Jul 11 2023 08:30

Reported on: Jul 12 2023 11:22

Ordered by: VANCOUVER COASTAL HEALTH (SECHLT)
Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHLT)

Printed on: 2023-07-14 10:43
Page 1 of 1

Test	Flag	Result	Reference Range - Units
------	------	--------	-------------------------

Sample: GIBSONS WATER SYSTEM
SITE 15 ARBUTUS REACH

Environmental Report

Environmental Water Samplings

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	Arbutus Reach	
System Type	WS1A	
Specimen Source	Deep Well	
Site Treatment	No	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental



Collected on: Jul 10 2023 09:50

Received on: Jul 11 2023 08:30

Reported on: Jul 12 2023 11:22

Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2023-07-14 10:43

Page 1 of 1

Test	Flag	Result	Reference Range - Units
------	------	--------	-------------------------

Sample: GIBSONS WATER SYSTEM
SITE 5 GIBSONS WAY

Environmental Report**Environmental Water Samplings**

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	Highway 101	
System Type	WS1A	
Specimen Source	Combined	
Site Treatment	Yes	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental



Collected on: Jul 10 2023 09:22

Received on: Jul 11 2023 08:30

Reported on: Jul 12 2023 11:22

Ordered by: VANCOUVER COASTAL HEALTH (SECHLT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHLT)

Printed on: 2023-07-14 10:43

Page 1 of 1

Test	Flag	Result	Reference Range - Units
------	------	--------	-------------------------

Sample: GIBSONS WATER SYSTEM
SITE 2 PARK ROAD

Environmental Report**Environmental Water Samplings**

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	Park Road	
System Type	WS1A	
Specimen Source	Combined	
Site Treatment	Yes	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental



Collected on: Jul 10 2023 09:11

Received on: Jul 11 2023 08:30

Reported on: Jul 12 2023 11:22

Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2023-07-14 10:43

Page 1 of 1

Test	Flag	Result	Reference Range - Units
------	------	--------	-------------------------

Sample: GIBSONS WATER SYSTEM
SITE 13 PARKLAND RESERVOIR SAMPLE PORT LOW

Environmental Report**Environmental Water Samplings**

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	Parkland	
System Type	WS1A	
Specimen Source	Deep Well	
Site Treatment	No	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental



Collected on: Jul 10 2023 09:42

Received on: Jul 11 2023 08:30

Reported on: Jul 12 2023 11:22

Ordered by: VANCOUVER COASTAL HEALTH (SECHLT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHLT)

Printed on: 2023-07-14 10:43

Page 1 of 1

Test	Flag	Result	Reference Range - Units
------	------	--------	-------------------------

Sample: GIBSONS WATER SYSTEM
SITE 14 DAVIS ROAD

Environmental Report**Environmental Water Samplings**

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	Davis Road	
System Type	WS1A	
Specimen Source	Deep Well	
Site Treatment	No	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental



Collected on: Jul 10 2023 09:37

Received on: Jul 11 2023 08:30

Reported on: Jul 12 2023 11:22

Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2023-07-14 10:43

Page 1 of 1

Test	Flag	Result	Reference Range - Units
------	------	--------	-------------------------

Sample: GIBSONS WATER SYSTEM
SITE 6 SHAW ROAD

Environmental Report**Environmental Water Samplings**

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	Shaw Road	
System Type	WS1A	
Specimen Source	Deep Well	
Site Treatment	No	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental



Collected on: Jul 19 2023 09:30

Received on: Jul 20 2023 08:30

Reported on: Jul 21 2023 14:46

Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2023-07-24 13:56

Page 1 of 1

Test	Flag	Result	Reference Range - Units
------	------	--------	-------------------------

Sample: GIBSONS WATER SYSTEM
SITE 13 PARKLAND RESERVOIR SAMPLE PORT LOW

Environmental Report**Environmental Water Samplings**

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	Parkland	
System Type	WS1A	
Specimen Source	Deep Well	
Site Treatment	No	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental



Collected on: Jul 19 2023 08:50

Received on: Jul 20 2023 08:30

Reported on: Jul 21 2023 14:46

Ordered by: VANCOUVER COASTAL HEALTH (SECHLT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHLT)

Printed on: 2023-07-24 13:56

Page 1 of 1

Test	Flag	Result	Reference Range - Units
------	------	--------	-------------------------

Sample: GIBSONS WATER SYSTEM
SITE 9 BALLS LANE

Environmental Report**Environmental Water Samplings**

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	Balls Lane	
System Type	WS1A	
Specimen Source	Deep Well	
Site Treatment	No	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental



Collected on: Jul 19 2023 09:00

Received on: Jul 20 2023 08:30

Reported on: Jul 21 2023 14:24

Ordered by: VANCOUVER COASTAL HEALTH (SECHLT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHLT)

Printed on: 2023-07-24 13:56

Page 1 of 1

Test	Flag	Result	Reference Range - Units
------	------	--------	-------------------------

Sample: GIBSONS WATER SYSTEM
SITE 10 SCHOOL ROAD RESERVOIR

Environmental Report**Environmental Water Samplings**

Sample Type	Drinking water	
Method	Enzyme Substrate	
Environmental Health Officer	Darren Molder	
Site Address	School Road	
System Type	WS1A	
Specimen Source	Deep Well	
Site Treatment	No	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental



Collected on: Jul 19 2023 09:12

Received on: Jul 20 2023 08:30

Reported on: Jul 21 2023 14:24

Ordered by: VANCOUVER COASTAL HEALTH (SECHLT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHLT)

Printed on: 2023-07-24 13:56

Page 1 of 1

Test	Flag	Result	Reference Range - Units
------	------	--------	-------------------------

Sample: GIBSONS WATER SYSTEM
SITE 6 SHAW ROAD

Environmental Report**Environmental Water Samplings**

Sample Type	Drinking water	
Method	Enzyme Substrate	
Environmental Health Officer	Darren Molder	
Site Address	Shaw Road	
System Type	WS1A	
Specimen Source	Deep Well	
Site Treatment	No	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental



Collected on: Jul 19 2023 08:36

Received on: Jul 20 2023 08:30

Reported on: Jul 21 2023 14:24

Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2023-07-24 13:56

Page 1 of 1

Test	Flag	Result	Reference Range - Units
------	------	--------	-------------------------

Sample: GIBSONS WATER SYSTEM
SITE 8 FRANKLIN ROAD

Environmental Report**Environmental Water Samplings**

Sample Type	Drinking water	
Method	Enzyme Substrate	
Environmental Health Officer	Darren Molder	
Site Address	Franklin Road	
System Type	WS1A	
Specimen Source	Deep Well	
Site Treatment	No	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental



Collected on: Jul 24 2023 09:37

Received on: Jul 25 2023 08:30

Reported on: Jul 26 2023 13:08

Ordered by: VANCOUVER COASTAL HEALTH (SECHLT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHLT)

Printed on: 2023-07-28 09:50

Page 1 of 1

Test	Flag	Result	Reference Range - Units
------	------	--------	-------------------------

Sample: GIBSONS WATER SYSTEM
SITE 6 SHAW ROAD

Environmental Report**Environmental Water Samplings**

Sample Type	Drinking water	
Method	Enzyme Substrate	
Environmental Health Officer	Darren Molder	
Site Address	Shaw Road	
System Type	WS1A	
Specimen Source	Deep Well	
Site Treatment	No	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental



Collected on: Jul 24 2023 09:54

Received on: Jul 25 2023 08:30

Reported on: Jul 26 2023 13:08

Ordered by: VANCOUVER COASTAL HEALTH (SECHLT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHLT)

Printed on: 2023-07-28 09:50

Page 1 of 1

Test	Flag	Result	Reference Range - Units
------	------	--------	-------------------------

Sample: GIBSONS WATER SYSTEM
SITE 5 GIBSONS WAY

Environmental Report**Environmental Water Samplings**

Sample Type	Drinking water	
Method	Enzyme Substrate	
Environmental Health Officer	Darren Molder	
Site Address	Highway 101	
System Type	WS1A	
Specimen Source	Combined	
Site Treatment	Yes	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental



Collected on: Jul 24 2023 10:22

Received on: Jul 25 2023 08:30

Reported on: Jul 26 2023 13:08

Ordered by: VANCOUVER COASTAL HEALTH (SECHLT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHLT)

Printed on: 2023-07-28 09:50

Page 1 of 1

Test	Flag	Result	Reference Range - Units
------	------	--------	-------------------------

Sample: GIBSONS WATER SYSTEM
WELL 1

Environmental Report**Environmental Water Samplings**

Sample Type	Drinking water	
Method	Enzyme Substrate	
Environmental Health Officer	Darren Molder	
Site Address	Gower Point Road	
System Type	WS1A	
Specimen Source	Deep Well	
Site Treatment	No	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental



Collected on: Jul 24 2023 10:18

Received on: Jul 25 2023 08:30

Reported on: Jul 26 2023 13:08

Ordered by: VANCOUVER COASTAL HEALTH (SECHLT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHLT)

Printed on: 2023-07-28 09:50

Page 1 of 1

Test	Flag	Result	Reference Range - Units
------	------	--------	-------------------------

Sample: GIBSONS WATER SYSTEM
WELL 4

Environmental Report**Environmental Water Samplings**

Sample Type	Drinking water	
Method	Enzyme Substrate	
Environmental Health Officer	Darren Molder	
Site Address	Gower Point Road	
System Type	WS1A	
Specimen Source	Deep Well	
Site Treatment	No	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental



Collected on: Jul 24 2023 11:57

Received on: Jul 25 2023 08:30

Reported on: Jul 26 2023 13:08

Ordered by: VANCOUVER COASTAL HEALTH (SECHLT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHLT)

Printed on: 2023-07-28 09:50

Page 1 of 1

Test	Flag	Result	Reference Range - Units
------	------	--------	-------------------------

Sample: GIBSONS WATER SYSTEM
SITE 15 ARBUTUS REACH

Environmental Report**Environmental Water Samplings**

Sample Type	Drinking water	
Method	Enzyme Substrate	
Environmental Health Officer	Darren Molder	
Site Address	Arbutus Reach	
System Type	WS1A	
Specimen Source	Deep Well	
Site Treatment	No	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental



Collected on: Jul 24 2023 09:31

Received on: Jul 25 2023 08:30

Reported on: Jul 26 2023 13:08

Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2023-07-28 09:50

Page 1 of 1

Test	Flag	Result	Reference Range - Units
------	------	--------	-------------------------

Sample: GIBSONS WATER SYSTEM
SITE 14 DAVIS ROAD

Environmental Report**Environmental Water Samplings**

Sample Type	Drinking water	
Method	Enzyme Substrate	
Environmental Health Officer	Darren Molder	
Site Address	Davis Road	
System Type	WS1A	
Specimen Source	Deep Well	
Site Treatment	No	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental



Collected on: Jul 24 2023 10:47

Received on: Jul 25 2023 08:30

Reported on: Jul 26 2023 13:08

Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2023-07-28 09:50

Page 1 of 1

Test	Flag	Result	Reference Range - Units
------	------	--------	-------------------------

Sample: GIBSONS WATER SYSTEM
SITE 9 BALLS LANE

Environmental Report**Environmental Water Samplings**

Sample Type	Drinking water	
Method	Enzyme Substrate	
Environmental Health Officer	Darren Molder	
Site Address	Balls Lane	
System Type	WS1A	
Specimen Source	Deep Well	
Site Treatment	No	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental



Collected on: Jul 24 2023 10:41

Received on: Jul 25 2023 08:30

Reported on: Jul 26 2023 13:08

Ordered by: VANCOUVER COASTAL HEALTH (SECHLT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHLT)

Printed on: 2023-07-28 09:50

Page 1 of 1

Test	Flag	Result	Reference Range - Units
------	------	--------	-------------------------

Sample: GIBSONS WATER SYSTEM
SITE 7 ABBS ROAD

Environmental Report**Environmental Water Samplings**

Sample Type	Drinking water	
Method	Enzyme Substrate	
Environmental Health Officer	Darren Molder	
Site Address	Abbs Road	
System Type	WS1A	
Specimen Source	Deep Well	
Site Treatment	No	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental



Collected on: Jul 24 2023 09:59

Received on: Jul 25 2023 08:30

Reported on: Jul 26 2023 13:08

Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2023-07-28 09:50

Page 1 of 1

Test	Flag	Result	Reference Range - Units
------	------	--------	-------------------------

Sample: GIBSONS WATER SYSTEM
SITE 4 KIWANIS

Environmental Report**Environmental Water Samplings**

Sample Type	Drinking water	
Method	Enzyme Substrate	
Environmental Health Officer	Darren Molder	
Site Address	Upper Gibsons	
System Type	WS1A	
Specimen Source	Combined	
Site Treatment	Yes	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental



Collected on: Jul 24 2023 10:07

Received on: Jul 25 2023 08:30

Reported on: Jul 26 2023 13:08

Ordered by: VANCOUVER COASTAL HEALTH (SECHLT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHLT)

Printed on: 2023-07-28 09:50

Page 1 of 1

Test	Flag	Result	Reference Range - Units
------	------	--------	-------------------------

Sample: GIBSONS WATER SYSTEM
SITE 10 SCHOOL ROAD RESERVOIR

Environmental Report**Environmental Water Samplings**

Sample Type	Drinking water	
Method	Enzyme Substrate	
Environmental Health Officer	Darren Molder	
Site Address	School Road	
System Type	WS1A	
Specimen Source	Deep Well	
Site Treatment	No	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental



Collected on: Jul 24 2023 10:29

Received on: Jul 25 2023 08:30

Reported on: Jul 26 2023 13:04

Ordered by: VANCOUVER COASTAL HEALTH (SECHLT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHLT)

Printed on: 2023-07-28 09:50

Page 1 of 1

Test	Flag	Result	Reference Range - Units
------	------	--------	-------------------------

Sample: GIBSONS WATER SYSTEM
WELL 3

Environmental Report**Environmental Water Samplings**

Sample Type	Drinking water	
Method	Enzyme Substrate	
Environmental Health Officer	Darren Molder	
Site Address	Winn T Gower Point Road	
System Type	WS1A	
Specimen Source	Deep Well	
Site Treatment	No	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental



Collected on: Jul 24 2023 09:42

Received on: Jul 25 2023 08:30

Reported on: Jul 26 2023 13:04

Ordered by: VANCOUVER COASTAL HEALTH (SECHLT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHLT)

Printed on: 2023-07-28 09:50

Page 1 of 1

Test	Flag	Result	Reference Range - Units
------	------	--------	-------------------------

Sample: GIBSONS WATER SYSTEM
WELL 6

Environmental Report**Environmental Water Samplings**

Sample Type	Drinking water	
Method	Enzyme Substrate	
Environmental Health Officer	Darren Molder	
Site Address	Oceanmount Blvd	
System Type	WS1A	
Specimen Source	Deep Well	
Site Treatment	No	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental



Collected on: Jul 24 2023 11:02

Received on: Jul 25 2023 08:30

Reported on: Jul 26 2023 13:04

Ordered by: VANCOUVER COASTAL HEALTH (SECHLT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHLT)

Printed on: 2023-07-28 09:50

Page 1 of 1

Test	Flag	Result	Reference Range - Units
------	------	--------	-------------------------

Sample: GIBSONS WATER SYSTEM
SITE 8 FRANKLIN ROAD

Environmental Report**Environmental Water Samplings**

Sample Type	Drinking water	
Method	Enzyme Substrate	
Environmental Health Officer	Darren Molder	
Site Address	Franklin Road	
System Type	WS1A	
Specimen Source	Deep Well	
Site Treatment	No	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental



Collected on: Jul 24 2023 09:14

Received on: Jul 25 2023 08:30

Reported on: Jul 26 2023 13:04

Ordered by: VANCOUVER COASTAL HEALTH (SECHLT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHLT)

Printed on: 2023-07-28 09:50

Page 1 of 1

Test	Flag	Result	Reference Range - Units
------	------	--------	-------------------------

Sample: GIBSONS WATER SYSTEM
SITE 2 PARK ROAD

Environmental Report**Environmental Water Samplings**

Sample Type	Drinking water	
Method	Enzyme Substrate	
Environmental Health Officer	Darren Molder	
Site Address	Park Road	
System Type	WS1A	
Specimen Source	Combined	
Site Treatment	Yes	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental



Collected on: Jul 24 2023 09:03

Received on: Jul 25 2023 08:30

Reported on: Jul 26 2023 12:49

Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2023-07-28 09:50

Page 1 of 1

Test	Flag	Result	Reference Range - Units
------	------	--------	-------------------------

Sample: GIBSONS WATER SYSTEM
SITE 13 PARKLAND RESERVOIR SAMPLE PORT LOW

Environmental Report**Environmental Water Samplings**

Sample Type	Drinking water	
Method	Enzyme Substrate	
Environmental Health Officer	Darren Molder	
Site Address	Parkland	
System Type	WS1A	
Specimen Source	Deep Well	
Site Treatment	No	
Total Coliform	4.2	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental



Collected on: Jul 05 2023 10:06

Received on: Jul 06 2023 08:30

Reported on: Jul 07 2023 11:13

Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2023-07-10 14:02

Page 1 of 1

Test	Flag	Result	Reference Range - Units
------	------	--------	-------------------------

Sample: GIBSONS WATER SYSTEM
SITE 8 FRANKLIN ROAD

Environmental Report**Environmental Water Samplings**

Sample Type	Drinking water	
Method	Membrane Filtration	
Environmental Health Officer	Darren Molder	
Site Address	Franklin Road	
System Type	WS1A	
Specimen Source	Deep Well	
Site Treatment	No	
Total Coliform	Less than 1	Count/100mL
Escherichia Coli	Less than 1	Count/100mL

Reported by: PHSA Environmental

Collected on: Jul 27 2023 08:30

Received on: Jul 28 2023 08:30

Reported on: Jul 31 2023 09:14



Ordered by: VANCOUVER COASTAL HEALTH (SECHELT)

Printed on: 2023-08-01 09:22

Reported to: BCCDC LAB COPY, VANCOUVER COASTAL HEALTH (SECHELT)

Page 1 of 1

Test	Flag	Result	Reference Range - Units
------	------	--------	-------------------------

Sample: GIBSONS WATER SYSTEM
SITE 13 PARKLAND RESERVOIR SAMPLE PORT LOW

Environmental Report**Environmental Water Samplings**

Sample Type	Drinking water	
Method	Enzyme Substrate	
Environmental Health Officer	Darren Molder	
Site Address	Parkland	
System Type	WS1A	
Specimen Source	Deep Well	
Site Treatment	No	
Total Coliform	25.4	Count/100mL
Escherichia Coli	Less than 1	Count/100mL